SENNHEISER

Firmware Update
AMBEO Soundbar Max

Firmware Version 1.0.272 (GLOBAL), 1.0.232 (CHINA-variant)

AMBEO Soundbar Max SB01
Sennheiser recommends to always install the latest firmware version to ensure the best performance of your product.

We have implemented the following

- Bugfix on certain Dolby True HD codecs which as led to distorted sounds
- New AMBEO Sub firmware #51 **with improved AMBEO Sub update mechanism.** Certain conditions have led to failing updates for some cases. We are sorry for the caused inconvenience. Please retry to update your AMBEO Sub, in case you failed with the last firmware release.

- **How to update the AMBEO Sub with the SB01?**
    - The update happens wirelessly over Bluetooth Low Energy. In order to facilitate the update, please make sure to remove the Subwoofer RCA cable <u>from the Subwoofer</u> in order to enable the wirelessly transmission capability.
        - If a Sub cable is connected to the Subwoofer-input of the AMBEO Sub, the LED on the Sub will turn green. = The data transmission is disabled to reduce power consumption.
        - Please disconnect the Sub RCA cable from the Subwoofer. The LED should be pulsating yellow to allow wireless data transmission
        - Go into Sennheiser Smart Control app, click on Firmware > "Update AMBEO Sub" and follow instructions.
        - If an AMBEO Sub is found and not updated yet, the AMBEO Sub will be updated automatically.
        - During update the LED will pulsate orange.
        - Once the update is finished, the Sub LED will again pulsate yellow.
        - Please connect the Sub cable again.
    - Please make sure to recalibrate the system again after the AMBEO Sub got updated.