

	AIRCRAFT RECO	AD - OLIVERAL III	OKMATION	
MANUFACTURER PIPER REGISTRATION NUMBER N5	1503			
REGISTRATION NUMBER	7505	DAT	E MFG	
MFG LYCOMING	MODEL 0 - 143	5-BZ	SERIAL _	2351
MFG	MODEL		SERIAL _	
PROPELLER(S) CURRENTLY INSTALLED. MFG		MODEL	1112	- 35
HUB MODEL				
BLADE MODEL	SERIAL	SERIAL		SERIAL

AIRCRAFT DECORD - GENERAL INFORMATION



DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
2-12	-91:	TNSP.	AIR	FRAME ALL CONTROLS & CABLES LUBE
AIRCK		-		C BRG'S REPLACE BRAKE CLIP IN BRAKE
TIGHT	EN 7	ALL WI	YEEL K	MOUNT BOLTS SERVICE TIRES & BRAKE
FLUI.	D REI	LACE	ELT	BATT. + CK OPERATION NEXT REPLACEMENT
DUE	12-9	72 1	00 4	7-50-3 CANVAS SEAT SLING C/W BY INSP.
BP	VOTES	115	TED ,	REAR OF LOG DATE 2-12-9/ I CERTIFY THAT THIS
				AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE
				WITH AN FINDURC INSPECTION AND WAS
				DETERMINED TO BE IN AIRWORTHY CONDITION.
				T.T. 1036.0 TACH
				Mele L. Fury IA 1500038

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
2-14	1-92	TIT	1040	.O INSP. AIRFRAME ALL CONTROLS &
CA	BLES			RCRAFT SERVICE TIRES & BRAKE FLUID
CK	ELT O	PERA	TION I	BATT. REPLACEMENT DUE 12-92 AD
47.	-50-3	CAN	VAS SI	FAT SLING C/W BY INSP. AD 68-5-1
EXI	4. 5TA	CKS	YW B	INSP. AD 77-3-8 STEEL LIFT STRUTS
Yw	BY &	MS	PUNCH	TEST NEXT INSP. DUE 2-14-97
AD	NOTES	LIS:	TED 1	REAR OF LOG
			· /	DATE 2-14-92 I CERTIFY THAT THIS
				WITH AN ANNUAL INSPECTION AND WAS
	0.7			DETERMINED TO BE IN AIRWORTHY CONDITION.
				LL_/OHO O TACH
				Mule L. Fund IA 1500038

19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
3-4	93	T.T.	1060	INSP. AIRFRAME ALL CONTROLS + CARLES
LUB	= AIR			K WHEEL BRG'S SERVICE TIRES + BRAKE
FLU.	10 GL	UE R	VODER	CABLE REINFORCEMENT POTCHES REPLACE
ELT	BAT	T. +	CK OI	PERATION NEXT REPLACEMENT DUE 2-95
WAS	H PIR	CRAFT	AD	47-50-3 CANVAS SEAT SLING YW BY INSP.
AD	NOTES	1157	ED RE	AR OF LOG 2-11-93
				DATE 3 4 93 I CERTIFY THAT THIS
				WITH AN ANY WAL INSPECTION AND WAS
			1 172	LI 1060 TAGH
				Mule L. Freny IA1500038
		33.	1 - 5	

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
4-20	7-94	T.T.	1062	INSP. AIRFRAME ALL CONTROLS + CABLES
LUB	E AIR			ICE TIRES + BRAKE FLUID REPAIR LEAK
BOTT	om AF	T EN	OF	FUEL TANK AD 93-10-6 WING STRUTS YW BY
INSF	+ TRE	ATING	WITH	LINSEED OIL DUE EVERY 2 YR, AD 47-50-3
				W BY INSP. AD 68-5-1 EXH- STACK YW BY INSP
WAS	H AIR	CRAFT	CK.	ELT OPERATION BATT. REPLACEMENT DUE 2-95
AD I	YOTES L	ISTED	REAR	DATE 4-20-94 I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE
				WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
				mule L. Fury IA1500038
		1		- The or years and the

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
5-19-	95 T.	T. 10	64.3	INSP. AIRFRAME ALL CONTROLS & CABLES
LUB	= AII	RCRAF	T 5E	RVICE TIRES + BRAKE FLUID REPLACE
ELT.	BAT	7. +	CK OP	ERATION NEXT REPLACEMENT DUE 6-97
AD	47-50	-3 (ANVA	SEAT SLING YOU BY THSP. AD 68-5-1 EXH
STAC	K C/w	By	INSP.	AD NOTES LISTED REAR OF LOG
				DATE 5-18-95 I CERTIFY THAT THIS
	-	- 3		AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE
			10	WITH AN ANYUAL INSPECTION AND WAS
				DETERMINED TO BE IN AIRWORTHY CONDITION.
				LL_1064,3 TACH
				Mule L. Fury IA1500038
1	7			

+

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
6-11	4-96	7.7.	1065	7 INSP. AIRFRAME ALL CONTROLS & CABLES
LUB	E AIR	CRAF	PACK	WHEEL BRG'S SERVICE TIRES & BRAKE FLUID
RECI	AMP	THROT	TLE CO.	HTROC HOUSING CK. ELT OPERATION BATT.
	Part and under our	P. Charles	Secretary and the second	-97 AD 93-10-6 WING STRUTS YW BY INSP
				OIL AD H7-50-3 CANVAS SEAT SLING YW
,	R OF			EXH. STACK YN BY INSP. AD NOTES LISTE
7.0			0.75.71.75.7	RAFT HAS BEEN INSPECTED IN ACCORDANCE AN HINNEY INSPECTION AND WAS
				RMINED TO BE IN AIRWORTHY CONDITION.
		47		A-0
		-	11/	ule L. Funy TA1500038
		-		

RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
97 I	NSP.	AIRF	RAME ALL CONTROLS + CABLES LUBE AIRCRAFT
RVICE	TIK	ES t	BRAKE FLUID STOP DRILL CRK L. REAR
VDOW	REP	LACE E	LT BATT. + CK OPERATION NEXT REPLACEMENT
7-99	AD	47-50	0-3 CANVAS SEAT SLING YW BY ENSP. AD 68-5-1
y. ST	ACK C	WW BY	INSP. AD NOTES LISTED REAR OF LOG
			1 12-97
			DATE 6-12-97 I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE
			WITH-AN ANNUAL INSPECTION AND WAS
			DETERMINED TO BE IN AIRWORTHY CONDITION.
			mule & Luny IA1500038
	TACH TIME -97 I RVICE VDOW - 7-99	TACH TODAYS FLIGHT -97 INSP. RUICE TIK 100W REP	TACH TODAYS TIME IN SERVICE -97 INSP. AIRF RUICE TIRES & 100W REPLACE & 7-98 AD 47-5

=

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
6-19	-98	INS	P. AIR	FRAME ALL CONTROLS + CABLES LUBE
	AIRCA	AFT	PACK	WHEEL BRG'S SERVICE TIRES + BRAKE
	FLUID	CK	ELT C	PERATION BATT REPLACEMENT DUE 7-99
	AD 4	7-50	-3 CA	NVAS SEAT SLING YW BY INSP. AD 93-10-6
				W BY INSP. + RE OIL WASH AIRCRAFT
				TE 6-19-98 I GERTIFY THAT THIS
			A	RCRAFT HAS BEEN INSPECTED IN ACCORDANCE
				THE AN ANNOTE INSPECTION AND WAS
				1. 1068.0 TACH -0
				Mule S. Fung I A 1500038

PAGES FOR OTHER SPECIFIC ENTRIES.)
LES LUBE AIRCRAFT
AILWHEEL ATTATCH
FIREWALL REPLACE
e 91.207 NEXT
AD 47-50-3
AD 99-1-5 WING
+ AIRCRAFT
THAT THIS
CCORDANCE
N AND WAS
DITION.
I TA 1500038

DATE 19	RECORDING TACH TIME	TODAYS	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
7-3	1-01	INSP.	HIRE	CAME ALL CONTROLS & CABLES LUBE AIRCRAFT
		-		BRAKES TIGHTEN TAIL SPRING CLAMP CK.
				AW FAR 91.2074 BATT. REPLACEMENT DUE
	3-00	AD	47-5	DATE 7-31-01 I CERTIFY THAT THIS
		-		AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL HOLDS AND WAS
				DETERMINED TO BE IN AIRWORTHY CONDITION.
				I.I. 1071.0 TACH 20
7.2			/	Mule L. Funy IA 1500038

DATE 2002	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
18-07	-02	Insp	ect flub	e Airframe controls cables Pulleys service brakes, tires
Whec	ckpitengi			Replaced left side sliding window Replace elt Battery and test
			1	ins lubecontrol sureface Hingos, elevator trim dack screw.
Complia	Vaith A	0 47-	50-03	Anus seatinsp. AD68-05-01RIEXTAUST Muffloxs AD 81-25-0
		10-99	-os- win	g struts. SEE AD compliance Report.
		I	certify	thatThis AiRCRAFT HAS been inspected IAW 100HR inspection
		A	nd for	ad to be in An Airworthy condition.
				Oh Ho 448642714 A:P
		¥8.	180	TT: 1073.5
				Time take in from Owners loy book flight ROURDS.
				ELT BAHERY due: July 04

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
	111		1 0 11	TOTAL A/C TIME 753.5 HRS. TACH TIME -
				ACCORDANCE WITH AN ICIRCLE ONE ANNUAL MOD HR INSPECTION AS PER PIPE MANUAL AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION. BY 2273823 1/A SIGNATURE GERTIFICATE NO.TYPE

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
is-25-05	1074.1			found to be in An Airwonthy condition c/u AD 47.50
				found to be in An Airwonthy condition c/u AD 47.50
				(SOATS) 99.01.05 (Struts) Replaced Elt 32thy due AP207 check
				Elt IAW far 91(201) d (64-16,4986) 774

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
				Corry that this Air frame has bee
				instricted in accordance suita - Annua
		11.9	೧೯೮೫ ಕಳೆ	worthy conditions the section with the section of t
				# 1749042 I.A.
			***	Sig. Dary W. Johnson
		15		/ /
				-186.2 TSO

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
				currity that this Air Framenas bee
				inspected in accordance with a Annual
				inspection and was determined to be in an air
		1	7	worthy condition.
				* 1749042 T.A.
				sig. Dang W. Johnson
		1 -		Sig. Jany W. Johnson Pate 4/11/06 Hrs. 1075.2 TTAR
		-		
-	1		-	

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
		7		Removed engine, propeller left Rear window Removed
7/7/07	TTAF	1108.	4	and Replaced Removed Brake master cylinders, Replaced diaphanges
				Rip upper brake lines installed grove disk brake corresion 15.t.
				Filled & Bled bankos. Dack wheel beneings install New 8'00x6
				tions & tubos. Installed Land pool tail whole. Rill GARD
1.45	10.9	E 181	Z2 33	heat cable, fuel shot official cable, fuel shot offuelve, oil
		2.5	1000	prossureline felprossure line, installed Now orginishock
				mounts, cleaned gascolaten. Roplaced elevation frimindicate
	D. Asis	. 84 7.7	Andr :	Installed OH'd orgine, Sensinich climb prop, installed New
j		1 4375	80.02	bungers on main gran checked control opbles in fiselage.
	1			C/W AD 47 50 -03 Seat pars
6				CIN AD 99-01-05 wing starts

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
				painted; installed wheel covers. Test TAX; ALL
				Jety- 1-1848642714
JULY	24, 200	7 AN	NUAC/	100 HOUR INSPECTION AS PEZ FAR 43 APP. (0) LUGE
				NISTALL NEW ELT. BATTERY, INSPECT + TEST PER
_	FAR 91.	207.	FABRICA	TE + TUSTALL SMALL CHAFFE PLATES FOR UPPER ALLEN
	TURNEL	CKLES	TO TOP	OF WINGS MADE FROM - 020 2024-T3 ALCLAD. CUT W
	YEA. A.	DOITIO	NAL AC	LESS HOLES ON EACH WING. RUN UP + TAXI. (LEAS FULL SUE
	CW. AD	47.50	03 BY UKS	PAL TASP. OF CANUASS PER \$6.45. DUE AGAIN 100 HOURS.
				SP. + PRESSURE TEST OF EXHAUST SYSTEM. DUE AGAIN SO HOURS.
				(CONT. NEXT PAGE)

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
7/24/67	(CONT)	A099-	01-05 w	AS COMPLIED WITH ON 7/7/07 BY INSPECTION AND
	PRESERU	ATION	OF WIN	STRUTS PER. 585280. DUE AGAIN 24 MONTHS.
	AD'S CL). NEU	LISTS C	REATED + UPDATED THRU REVISION 2007-14F.
	SUBMIT	FORM	337 FO	R BRAKE SYSTEM INSTALLATION PER STC. SAOITOYLA
	TO FA			AP567022519
		Т.Т.	ALRERA	I CERTIFY THAT THIS
	2.15	ELT.	BATTERY	WAS DETERMINED IN AIRWORTHY CONDITION
				DATE 7-24-07 / 1/08.4 HRS.
				SIGNATURE
				CERTIFICATE NO. APS 47022519IA
	-			

19 <u>0</u> 7	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
7-2507		1.0		1st hour on new engine
1-29-07		+0		CONTRACTOR SERVICES AND MINISTER CONTRACTOR
		4		
8/31/07	TTAF:	1119.7	GENE	RAL INSPECTION OF AIRCRAFT, FABRICATE + THUSAL
				ES FOR OB. AFT RUDDER PRUMES. Z.M. APSG70225174
12/12/07	TTAF:	1130.0	GENER	AL FUSARCTION OF AIRCRAFT. SERVICE L+R BRAKE SYSTEM
1		erieven Sei efformer	1 2 - 1 1 - 1 + 1 + 1 + 2 - 3	2 APS670225 19IA.
46	TICLUS :	HALL		MATERIA CAN
		>= -(****)		LINUTAKED COMPANY TO THE PROPERTY OF THE PROPE
	* x 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			

	TOTAL IN			C. Berr Reco.		NS
	SERVICE (Quality Aero Main	ntenance			BER C
		00 E. Jahant Rd.,	Hanger C			
		, CA., 95220 PH	-	040		
		AIRFRAM				-
Reg#:N51503	Date:9/26/2008	Tach:N/A TT	AF:1133.9	ELT battery du	ie:Sep.2009	_
Annual / 100 Hour is entire airframe. Patc						
and test ELT per FA CW AD47-50-03 by CW AD68-05-01 by 50hrs.	R.91.207. Inspect inspection of can	propeller, re-toro vass per SB.45. I	que mount be Due again wi	olts and re-safety thin 100hrs.	<i>'</i> .	
and test ELT per FA CW AD47-50-03 by CW AD68-05-01 by	R.91.207. Inspect inspection of can visual inspection	propeller, re-tord vass per SB.45. I and pressure/soa	que mount be Due again wi	olts and re-safety thin 100hrs.	<i>'</i> .	
and test ELT per FA CW AD47-50-03 by CW AD68-05-01 by 50hrs.	R.91.207. Inspect inspection of can visual inspection	propeller, re-tord vass per SB.45. I and pressure/soa	que mount be Due again wi p test of exh	olts and re-safety thin 100hrs.	e again within	

		Quality Aero Maint					
	3700 E. Jahant Rd., Hanger C						
	Acamp	o, CA., 95220 PH(209)366-1040				
		AIRFRAME					
	Reg.#:N51503	Date:4/15/2009	TT Airframe: 1141.2				
AIL-G-27500-20 nagneto housings inshielded 6 gauge	shielded 20 gauge a Install grounding of	approved copper air	h through magneto ground terminals using craft wire. Ground the wire shielding to o engine mount using MS22759/16-6 was accomplished to eliminate radio				
tatic.			7.11				
tatic.			Frank Madden AP567022519I.				
tatic.							
tatic.							
tatic.							
tatic.							
tatic.							

_		
D.	Chighty Aero Maintenance	IONS
19	3700 E. Jahant Rd., Hanger C	UMBER OF ENTRIES.)
_	Acampo, CA., 95220 PH.(209)366-1040	
	AIRFRAME	
_	Reg.#:N51503 Date:9/10/2009 Tach:N/A TT.Airframe:1147.6 ELT battery due:Nov.2011	
_	Annual / 100 Hour inspection and service as per FAR. 43 App.(D). Service tires and brakes, and lube entire airframe. Pack all wheel bearings. Inspect and test ELT as per FAR. 91.207. Clean main	
_	and inlet fuel screens. Wipe down belly. Run up and taxi aircraft. Install new ELT battery and re-	
_	test. Re-torque engine to mount and propeller to engine bolts/nuts. Stop drill 2ea. cracks in top left engine baffle. Install 2ea. new adel clamps for engine crankcase vent tube support. Inspect propeller.	
_	CW AD47-50-03 by inspection of canvass seat per SB.45. Due again100hrs.	
	CW AD68-05-01 by visual inspection and pressure/soap test of exhaust system. Due again 50hrs.	
_	AD's CW and lists updated thru revision 2009-18F.	
_		
	Frank Madden AP567022519	
_		
_	I certify that this Airframe has been inspected in accordance with an Annual Inspection and was	
	determined to be in Airworthy Condition.	
_	E IN II I PROGRAMME	
_	Frank Madden AP567022519IA	

D.175	T	Quality Aero Maintenance	_
DATE	K	23987 N. Highway 99)F
19		Acampo, CA., 95220 PH.(209)366-1040	5.)
	+	AIRFRAME	_
		Reg.#:N51503 Date:10/1/2010 TT.Airframe:1166.7	
	T	ELT battery due:November 2011	
	+	Annual / 100 Hour inspection and service as per FAR. 43 App.(D). Service tires, brakes, and lube entire airframe. Pack main wheel bearings. Inspect and test ELT as per FAR. 91.207. Clean main	-
	+	and inlet fuel screens. Pressure/Soap test and inspect exhaust system. Wipe down belly. Run up and taxi aircraft. Install new oil pressure hose and fuel hose between shutoff and strainer. Re-attach	-
	1	velcro on rear seat with contact cement. Dope and patch small rip in fabric at inboard side of upper	
	1	right aileron cable cutout. Inspect propeller-no defects. CW AD47-50-03 by visual inspection of	_
	+	canvas seats per SB 45. Due again in 100hrs. CW AD68-05-01 by inspection and pressure/soap test	-
		of exhaust system. Due again in 50hrs. CW AD99-01-05 by inspection and preservation of struts	
		with linseed oil per SB 528D. Due again in 24 months.	
	+	AD's CW and lists updated through revision 2010-19F.	-
	+	Frank Madden AP567022519	_
		I certify that this aircraft has been inspected in accordance with an Annual Inspection and was	
_	+	determined to be in Airworthy Condition.	_
		determined to be in the world, condition.	
	T	Frank Madden AP567022519IA	

DAT	Quality Aero Maintenance	INS
19_	23987 N. Highway 99	NTRIES.)
	Acampo, CA., 95220 PH.(209)366-1040	.ivinico./
	AIRFRAME	
	Reg.#:N51503 Date:9/19/2011 TT.Airframe: 1185.7 TT Propeller:Unknown SPOH:77.3	
	Logged flight time since last Annual:19.0 ELT battery due:Dec 2013	
	Annual / 100 Hour inspection and service as per FAR 43 App (D) Service tires, brakes, and lube	
	entire airframe. Pack wheel bearings. Inspect and test ELT as per FAR 91.207. Clean main and inlet	
_	fuel screens. Pressure/Soap test and inspect exhaust system. Wipe down belly. Run up and taxi aircraft. Inspect propeller, re-torque per hub instructions and re-safety. Replace ELT battery and	
	re test. Install new fuel quick drain valve in main fuel sump. Add spacer washers as required and re	
	torque engine mount nuts/bolts. CW AD47-50-03 by visual inspection of canvass seats per SB 45.	
_	Due again in 100hrs. CW AD68-05-01 by inspection and pressure/soap test of exhaust system. Due	
	again in 50hrs. AD's CW and lists updated thru rev 2011-71EZU.	
	Zall	
	Frank Madden AP567022519	
	I certify that this aircraft has been inspected in accordance with an Annual Inspection and was	
	determined to be in Airworthy Condition.	
_		
	Frank Madden AP567022519IA	
	*	

Quality Aero Maintenance	
23987 N. Highway 99 Acampo, CA 95220 PH. (209) 366-1040	,
AIRFRAME	
Reg.#: N51503 Date: 11/7/13 TT Airframe: 1185.7 TT Prop: Unknown SPOH: 77.3	
Logged flight time since last Annual: 0.0 ELT battery due: Jan 16	
Annual /100 Hour inspection and service as per FAR 43 App (D). Service tires, brakes, and lube	-
entire airframe. Pack wheel bearings. Inspect, and install new battery (P/N BP-1045) and test ELT	-
as per FAR 91.207. Clean main and inlet fuel screens. Run up and taxi aircraft. Install two new fuel	
primer O-rings, P/N MS29513-012. Clean and reseal compass and service using kit number	
C-21-KF. Install four new landing gear shock cord rings, P/N 1280 HD. Recommended time change	-
in five years. CW AD 47-50-03 by visual inspection of canvas seats per SB 45. Due again in 100	
hours. CW AD 68-05-01 by inspection and pressure test of exhaust system. Due again in 50 hours.	-
CW AD 99-01-05 by inspection and preservation of wing struts with linseed oil per SB 528D. Due again in 24 months. AD 2012-03-07 N/A, carburetor model not installed. AD's CW and lists	-
updated through ATP content revision 11/5/2013.	
updated through ATT content revision 11/3/2013.	
Robert R. Kempf 573173800AP	-
I certify that this aircraft has been inspected in accordance with an Annual Inspection and was	-
determined to be in Airworthy Condition.	-
Robert R. Kempf AP573173800IA	_

Reg.#: N	10	-1040 ΓΑ F : 1186.7	

D 15	23987 N. Highway 99/P.O. Box 208 Acampo, CA 95220 PH (209) 366-1040 AIRFRAME Reg.#: N51503 Date: 12/8/14 TTAF: 1186.7 Logged flight time since last Annual 1.0 ELT battery due: Jan 17	TIONS NUMBER OF C ENTRIES.)
	Annual /100 Hour Inspection and service as per FAR 43 App (D). Service tires, brakes, and lube entire airframe. Pack all wheel bearings. Inspect, install battery P/N BP-1045 and test ELT as per FAR 91.207. Clean main and inlet fuel screens. Wipe down belly. CW AD 47-50-03 by visual inspection of canvas seats per SB-45. Due again in 100 hours. CW AD 68-05-01 by inspection and pressure test of exhaust system. Due again in 50 hours. AD 99-01-05 R1 C PCW prior to revision and no changes needed. Due in Nov 2015. AD's CW and lists updated through ATP content revision 12/5/2014. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition. Robert R. Kempf AP573173800IA	

DAT 19_	Quality Aero Maintenance 23987 N. Highway 99/P.O. Box 208 Acampo, CA 95220 PH (209) 366-1040 AIRFRAME	ONS MBER OF ENTRIES.)
_	Reg.#: N51503 Date: 11/17/16 TTAF: 1187.8 TT Prop: Unknown SPOH: 79.4	
_	Logged flight time since last Annual: 2.1 ELT battery due: Jan '17	
	Annual /100 Hour Inspection and service as per FAR 43 App (D). Service tires, brakes, and lube entire	
	airframe. Pack wheel bearings. Inspect and test ELT as per FAR 91.207. Wipe down belly. CW AD	
-	47-50-03 by visual inspection of canvas seats per SB 45. Due again in 100 hours. CW AD 68-05-01 by	
_	inspection and pressure test of exhaust system. Due again in 50 hours. CW AD 2015-08-04 by inspection and preservation of wing struts with linseed oil per SB 528D. Due again in 24 months. AD's	
	CW and lists updated through ATP content revision 11/15/2016.	
_	I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.	
_		
_	Robert R. Kempf AP573173800IA	
_		

19	Quality Aero Maintenance 23987 N. Highway 99/P.O. Box 208 Acampo, CA 95220 PH (209) 366-1040 AIRFRAME Reg.#: N51503 Date: 8/8/18 TTAF: 1189.9 TT Prop: Unknown SPOH: 81.4 Logged flight time since last Annual: 2.0 ELT battery due Oct 20 Annual /100 Hour Inspection and service as per FAR 43 App (D). Service tires, brakes, and lube entire airframe. Pack wheel bearings. Inspect, and install new battery (P/N BP-1045) and test ELT as per FAR 91.207. Clean and reseal compass and service using kit (P/N JMCRK). Install four new landing gear shock cord rings, (P/N 1280 HD). Recommended time change in five years. Wipe down belly. Dope and patch small rip in fabric at outboard side of upper right aileron cable cutout. CW AD 47-50-03 by visual inspection of canvas seats per SB 45. Due again in 100 hours. CW AD 68-05-01 by inspection and pressure test of exhaust system. Due again in 50 hours. CW AD 2015-08-04 by inspection and preservation of wing struts with linseed oil per SB 528D. Due again in 24 months. AD's CW and lists updated through ATP content revision 08/07/2018. I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition. Robert R. Kempf AP573173800IA	SER OF STRIES.)

		Quality Aero Mainten	ance		
	2398	37 N. Highway 99/P.O 50, CA 95220 PH (20	. Box 208		TE NUMBER OF
	Admi	AIRFRAME			CIFIC ENTRIES.)
N51503	Date: 1/15/20		TT Prop: Unknown		
			ction. ELT battery d		
				brakes, and lube entire	
airframe. Inspect who				tom. CW AD 47-50-03	
by visual inspection					
inspection and pressu					
through ATP content	revision 01/14/202	20.		2	
I certify that this airc			with an Annual Insp	ction and was	
determined to be in A	Airworthy Condition	n.	Pahart B Var	of AP573173800IA	
			Robert R. Kem	pi AP3/31/3600IA	
		11			
	1				
	-	100			
					and the proof of

DATE 19	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
10-21-100	11929			Librel and checked pil controls protect with All
				Nos checked and CAD at this clots This Airons of
				has been inspected in necondaine with an amount
				inspection and was Sound to be in an airwathy
				condition on this Date
				Wirling Jour town
				IN 52886 6595 AHP
10-21-23			11929	This ELT has been inspected and tested Per FAR 91.20
				OPERATION VOK NEW Battery installed NERT Battery Due
				10-25
				Wisher Fourtain
				In52868595A+P

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
18-2021		-11	1199.4	Both wings Right and Left Repoblic with Poly Stits
				Poly Fibra Procedure Money 1 #2 All conting including poly Fibra
			-	yellow PT#146. Labed and inspected all contracts Alls. Ds
				C/wat this date I centily that this nieces for has been
				and was found to be in an Airwarthy condition
				on this data
				Michou Four Kamow
			F	FASZ8868595A+P
8-2024			119514	This ELT has been inspected and tested Par Fax 91.2070
				operation test VOK NEXT Bottery De 10 pors Michaelandans
			1	TD5285E8595AHP

_		
1	Quality Aero Maintenance	ATIONS
,	23987 N. Highway 99/P.O. Box 208	NUMBER OF
	Acampo, CA 95220 PH (209) 366-1040	C ENTRIES.
	AIRFRAME	
_	N51503 Date: 7/7/21 TTAF: 1191.9	
	ELT battery due: June '23	
_	Annual /100 Hour Inspection and service as per FAR 43 App (D). Service tires, brakes, and lube	
	anting sinforms. Inspection and service as per 174K 45 App (D). Service thes, States, and FAR	
	entire airframe. Inspect wheel bearings. Inspect, install batter BP-1045 and test ELT as per FAR	
_	91.207. CW AD 47-50-03 by visual inspection of canvas seats per SB 45. Due again in 100 hours.	
	CW AD 68-05-01 by inspection and pressure test of exhaust system. Due again in 50 hours. CW	
_	AD 2015-08-04 by inspection and preservation of wing struts with linseed oil per SB 528D. Due	
	again in 24 months. AD's CW and lists updated through ATP content revision 1/14/2020.	
_	I certify that this aircraft has been inspected in accordance with an Annual Inspection and was	
	Teering that this ancian has been hispected in decordance with an in the	
-	determined to be in Airworthy Condition. Robert R. Kempf AP573173800IA	
	Robert R. Reliipi Al 3/31/300011	



ASA-SE-1

Manufacturer LYcomine	Model 0-1	US-B2
Serial 0145BZ SN This engine is currently installed in aircraf	-235 n	pe Certificate = 210-4
Minimum Octane Fuel	Oil Grade: Summer	Winter
Magneto Time	Point Setting	Firing Order
Spark Plug Gap	-	
Manufacturer recommended overhaul at _	hours	
	Address	

YEAR: 2007	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6-1-07			800:a	TOTAL TIME sence WEW, LAST MON 11-15-61
				TOTAL TIME THAT DATE 568:0. TIME TO DATE
				SINCE (45T OH 232!2
				Engene Received as removed fr A/c loth
				2 mags IngHaences, Stlengs, Carlos
				Engine Dismonted, allremobil Parts Out
				Cleany, Blother (3) 4 MAS/245 NO Trepent
				Chlytican Hay Polish, Block 5 Honey & Argh
				all galves Ryou & Firsp. 4ea Gol Head & sign
		. ta.		sent for mor as rego Clepants replace
				Sterry O H: Leab, Syrhot, Hoses, Rotonko
-				Jech Slotes, Bras, Dudge Tubes, Accy the

YEAR: RECORDING TODAY'S TOTAL Description of Inspections, Tests, Repairs and Alterations FLIGHT TIME IN TACH Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TIME SERVICE Facility. (See back pages for other specific entries.) DATE Feedler 5:30 805:30Te 4:30 810:00C LOUISONDA P. Hackenburg Aviation Lycoming R-680 Service Montoursville, PA 17754 570 (20) 368-8849

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair
DATE		l- I		Facility. (See back pages for other specific entries.)
			. 7	
			-	
Jd x07	SmoH.	10.0		install engine on New mounts, Add Sats Acroshell miner
7		1108.4		oil (sout) installed prop. tost REWN, fixed oil looks tost RAL
	1-117	110 0.1	- 1 - 1	on sour hand prop. Test took, fixed on Texts the
	to the to		1. 1. 52	DO lopks installed exhaust system provided by O. H shop
11 11			1, 1,	Of A A: 044864274
				477 47 (1867)
\$ 000		-1	- 12 11	
91110	SMOIL	10.2		found oil leakage under Are tightend case, oil ppn
70	37.40	10.0		
1.	1			Accossorie case Bolts.
. 400				Oh H_ A; ? 44869271
	- 3			917
	11 4 -1	1		

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7/24	107. A	NUA	1100 H	OUR TNSPECTION. COMPACSSION TEST: #1-7480, #2-7880
	#3-78/80,	=4-74	o. CHEC	K MAGNETO TIMING. CLEAN INCET FUEL SCREEN + DRAIN
				NSPECT - PRESSURE /SOMP TEST EXHAUST SYSTEM. CLEAN &
	GAP SPA	RE PLU	as. WA	SH DOWN ENGINE + CUBE CONTROLS. RE-WORK THREADS ON
	EXHAUST	HANGE	e Rods.	ADJUST MIXTURE 13 TURN LEAN. RUN UP + OPS CHECK.
1.00	OK. +N	DEA	us. Ins	PROPERCE.
-11	AD'SC4	0. + 41	STS UPD	ATED THRU REVISION 2007-14F. 2 APS67022519Id
-	100	TT.	ENGINE	: 784.4 I CERTIFY THAT THIS ENGINE HAS
	100	ENGI	VE SMOI	BEEN INSPECTED IN ACCORDANCE WITH. AND
		P. 100 100 100 100		: 1108.4 WAS DETERMINED IN AIRWORTHY CONDITION
				DATE 7-24-07 / 784.4 70744 HRS.
	1, -1303	05::1		CERTIFICATE NO. JAPS 620225194

OT DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
-25-07	1.0	1.0	(.0	1st hour on new engine
	4 1 353			
8/10/07	TTE: 78	5.4.7	TAF. (NE	1503): 1109.4. REMOVE MAGNETOS + TGNITION
1.0				KELLEY AEROSPACE OVERHAULED MAGNETOS. MODEL
_5.00	54LN-2	LLEF	+ 340	N-20 RIGHT PN: 10-51360-37 LEFT, 10-51360-29.
	SN's; G	10265	3 LEFT.	+ HOIO408 RIGHT. WO #13 329130 WET + M4 07840.
S	INSTA	cc.No	W IGN	TION HARNESSES ASSEMBLED BY J.P. HACKENBURG
248	+SONS.	Time	BOTH M	AGNETOS TO 23.5 %BTOC. BASED ON THE MOST CHERENT
	INFORM	ATION	REMOV	E CARBURETOR + RE-INSTALL AFTER MAIN JET REP-
MOSTE	LACEME	NT. (CEAN +	GAR SPARK PLUGS. START + RUN UP: GOOD + STARTS
HRS.	UERY E	PS/LY	WITH L	EFT EMPULSE NOW INSTALLED.
	1. 1. 3. 3	2 2 1 2	GLOUIST/	24 APS67022519IA.

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
8/31/07	TTE:	95.7	TTAF.(N	51503): 1119.7. CHANGE OIL. SERVICE S/40TS. OF
			10	DOWN ENGINE AND RUN UP. ENGINE SMOH = 11.3
				= APSL7022519IA.
12/126	TTE:	806.0	TTAF:	1130.0. CHANGE OIL. SERVICE W/4 RTS. OF AEROSHELL
	80 min	CRAL	DIL. IN	STACE NEW OIL PAN GASKET. WASH DOWN ENGINE + RUN
	UP-OF	ATT	HIS TIME	NO LLAKS. ZARS670ZZS19IA.
_				
			-	

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technic Facility. (See back pages for other specific entries.)	cian or Repair
DATE				racinty. (See back pages for other specific entries.)	1 - 12
7				Quality Aero Maintenance	150
				3700 E. Jahant Rd., Hanger C	
41			Aca	ampo, CA., 95220 PH.(209)366-1040	
?				ENGINE	
		Date	:9/26/2008	Tach: N/A TT.Engine: 809.9 Installed in: N51503	
ě.				OH:35.5 STOH:N/A DOH:6/1/2007	
				service. Change oil. Service with 4qts. of Aeroshell 80 (40wt).	_
-				73/80, #3=72/80, #4=71/80. Clean, gap and rotate spark plugs.	1 4
				el inlet screen and drain carburetor bowl. Pressure/Soap test and	
				wn engine and lube controls. Install new top cover gasket. Adjust	
-				ocker cover gaskets with new. Tighten tach drive to engine packing	
				p on right side. Run up. revision 2008-19F. None applicable this date.	
_					
	A CONTRACT CONTRACT	this andi	no has been	increated in accordance with an Annual/100 hour Increation and	
				inspected in accordance with an Annual/100 hour Inspection and	
_			ine has been Airworthy Co	[이미 시민구입	

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair
DATE		1	1004	Facility. (See back pages for other specific entries.)
				Quality Aero Maintenance
	1			3700 E. Jahant Rd., Hanger C
	+			Acampo, CA., 95220 PH.(209)366-1040
				ENGINE
		I	Date:9/10/20	009 Tach:N/A TT.Engine:849.2 Installed in:N51530
	-			SMOH:49.2 STOH:N/A DOH:6/1/2007
	mineral plugs. C and insp AD's C I certify). Compre Check may pect exhau W and list that this	gneto timing ust system. Its updated the Engine has	and service. Change oil. Service with 4qts. of Aeroshell 80 (40wt #1=70/80, #2=78/80, #3=71/80, #4=68/80. Clean, gap and rotate spark g. Clean fuel inlet screen and drain carburetor bowl. Pressure/Soap test Wash down engine and lube controls. Run up and check for leaks. hru revision 2009-18F. been inspected in accordance with an Annual/100 hour Inspection and worthy Condition.
				Frank Madden AP567022519IA
	1			

YEAR:	Quality Aero Maintenance 23987 N. Highway 99	Repair
DATE	Acampo, CA., 95220 PH.(209)366-1040 ENGINE	
	Date:10/1/2010 TTAF(N51503):1166.7 TT.Engine:868.3 Installed in:N51503 SMOH:68.3 STOH:N/A DOH:6/1/2007	
	Annual / 100 hour inspection and service. Change oil. Service with 4qts. of Aeroshell 100(50wt) mineral oil. Compression test: #1=70/80, #2=78/80, #3=73/80, #4=62/80. Clean, gap, and rotate spark plugs. Check magneto timing. Clean fuel inlet screen and drain carburetor bowl. Pressure/Soap test and inspect exhaust system. Wash down engine and lube controls. Run up. Recheck lifter clearances-OK and replace all rocker cover gaskets. Torque all head nuts as recommended by the overhaul facility, J. P. Hackenburg Aviation. Re-torque rocker pin bolts. AD's CW and lists updated through revision 2010-19F. I certify that this engine has been inspected in accordance with an Annual/100 hour inspection and was determined to be in Airworthy Condition.	
	Frank Madden AP567022519IA	· -

YEAR:	TACI	Quality Aero Maintenance							
	TIME	23987 N. Highway 99							
DATE		Acampo, CA., 95220 PH.(209)366-1040							
	17-	ENGINE	i li						
		Date:9/19/2011 Time run since last Annual:19.0 TT.Engine:887.3	_						
		Installed in:N51503 SMOH:87.3 STOH:N/A DOH:6/1/2007 Annual / 100 hour inspection and service. Change oil. Service with 4qts of Aeroshell 80(40wt)	-						
		mineral oil. Compression test: #1=66/80, #2=76/80, #3=72/80, #4=19/80. Clean, gap, and rotate							
	-	spark plugs. Check magneto timing. Clean fuel inlet screen and drain carburetor bowl. Pressure/	_						
		Soap test and inspect exhaust system. Wash down engine and lube controls. Remove #4 valve cover,							
	1	inspect and check valve clearances-OK. Stake exhaust valve and re-check #4 compression=64/80-							
	7.5	OK. Re-install rocker cover with new gasket. Borescope inspect all cylinders: Some light pitting but	_						
		otherwise OK. Run up. AD's CW and lists updated thru revision 2011-71EZU.							
	_	I certify that this engine has been inspected in accordance with an Annual/100 hour inspection and	_						
		was determined to be in Airworthy Condition.	_						
		F 1 W 11 A DS C 7000 S 10 W							
	-	Frank Madden AP567022519IA	_						
	1								
	_		_						
			_						

plugs. pect d ed	SMOH: 87.3 STOH: N/A DOH: 6/1/07 Annual/100 hour inspection and service. Change oil. Service with 4 quarts of Aeroshell 80 mineral oil. Compression test: #1=63/80, #2=78/80, #3=72/80, #4=64/80. Clean, gap, and rotate spark plugs. Check magneto timing. Clean fuel inlet screen and drain carburetor bowl. Pressure test and inspect exhaust system IAW AD 68-05-01. Retorque and safety propeller bolts. Wash down engine and lube controls. Run up, static RPM 2350. Check for leaks, none noted. AD's CW and lists updated through ATP content revision 11/5/2013. I certify that this engine has been inspected in accordance with an Annual/100 hour inspection and was determined to be in Airworthy Condition.
	Robert R. Kempf AP573173800IA
IA	
00	

	Quality Aero Maintenance 23987 N. Highway 99/P.O. Box 208 Acampo, CA 95220 PH.(209) 366-1040 ENGINE	nnician or Repair
Annual/100 hour Insp Compression test: #1= magneto timing. Clear controls. Retorque and through ATP content	Flight time since last Annual: 1.0 Installed in: N51503 TT Eng: 888.3 SMOH: 88.3 STOH: N/A DOH: 6/1/07 section and service. Change oil. Service with 4 quarts of Aeroshell 80 mineral oil. =75/80, #2=73/80, #3=/80, #4=70/80. Clean, gap, and rotate spark plugs. Check in fuel inlet screen and drain carburetor bowl. Wash down engine and lube d safety propeller bolts. Run up and check for leaks, none noted. AD list updated revision 12/5/2014.	

YE.	Quality Aero Maintenance 23987 N. Highway 99/P.O. Box 208 Acampo, CA 95220 PH.(209) 366-1040	an or Repair
DA.	ENGINE TO A STATE LIGHT OF THE PARTY OF THE	
	Date: 11/17/16 Installed in: N51503 TTAF: 1187.8	
_	TT Engine: 889.4 SMOH: 89.4 DOH: 6/1/07	
_	Annual/100 hour Inspection and service. Change oil. Service with 4 quarts of Aeroshell 80 mineral. Compression test: #1=70/80, #2=77/80, #3=74/80, #4=70/80. Clean, gap, and rotate spark plugs. Check magneto timing. Drain carburetor bowl. Wash down engine and lube controls. Run up and check for	
	leaks, none noted. AD list updated through ATP content revision 11/15/2016, none apply this date.	
_	I certify that this engine has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.	
_	Robert R. Kempf AP573173800IA	
		-
_		

R:	Quality Aero Maintenance 23987 N. Highway 99/P.O. Box 208	Janair					
_	Acampo, CA 95220 PH.(209) 366-1040	Repair					
E	ENGINE						
	Date: 8/8/18 Installed in: N51503 TTAF: 1189.8 TT Engine: 891.4 SMOH: 91.4 DOH: 6/1/07 Annual/100 hour Inspection and service. Change oil. Service with 4 quarts of Aeroshell 80 mineral. Compression test: #1=77/80, #2=70/80, #3=64/80, #4=70/80. Clean, gap, and rotate spark plugs. Check magneto timing. Drain carburetor bowl. Wash down engine and lube controls. Remove propeller for engine access and reinstall and torque. Run up and check for leaks, none noted. AD 2017-16-11 N/A by no work done to connecting rods during timeframe. AD list updated through ATP content revision 08/07/2018, none apply this date. I certify that this engine has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.						
-							
-							

Y	Quality Aero Maintenance						
	23987 N. Highway 99/P.O. Box 208	cian or Repa					
73	Acampo, CA 95220 PH.(209) 366-1040						
D	ENGINE						
	N51503 Date: 1/15/20 TTAF: 1189.8						
-	TT Engine: 891.4 SMOH: 91.4 DOH: 6/1/07						
4	Annual/100 hour Inspection and service. Change oil. Service with 4 quarts of Aeroshell W80.						
	Compression test: #1=68/80, #2=75/80, #3=72/80, #4=60/80. Clean, gap, and rotate spark plugs.						
٦.	Borescope cylinders. Check magneto timing. Clean fuel inlet screen and drain carburetor bowl. Lube						
	controls. Retorque propeller and safety. Run up and check for leaks, none noted. AD list updated through ATP content revision 01/14/2020, none apply this date.						
1							
	I certify that this engine has been inspected in accordance with an Annual Inspection and was						
- 1	I certify that this engine has been inspected in accordance with an Annual Inspection and was						
- 1	I certify that this engine has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition.						
- 1	I certify that this engine has been inspected in accordance with an Annual Inspection and was determined to be in Airworthy Condition. Robert R. Kempf AP573173800IA						
- 1	determined to be in Airworthy Condition.						
- 1	determined to be in Airworthy Condition.						
- 1	determined to be in Airworthy Condition.						
- 1	determined to be in Airworthy Condition.						
- 1	determined to be in Airworthy Condition.						
- 1	determined to be in Airworthy Condition.						
- 1	determined to be in Airworthy Condition.						
- 1	determined to be in Airworthy Condition.						
- 1	determined to be in Airworthy Condition.						

E		Q	uality Aero Mainten	ance			
			N. Highway 99/P.O.			ian or Repair	
	Acampo, CA 95220 PH.(209) 366-1040						
•			ENGINE				
		N51503	Date: 7/7/21	TTAF: 1191.9			
	TT Engine: 893.4	SMOH: 93.4		TT Prop: Unknown	SPOH: 83.4		
Anı	nual/100 hour Inspectio			[- [- [- [- [- [- [- [- [- [-			
	=75/80. Clean, gap, and						
			-		_		
	down engine and lube controls. Retorque propeller and safety. Run up and check for leaks, none noted. AD list updated through ATP content revision 1/14/2020, none apply this date.						
	I certify that this engine has been inspected in accordance with an Annual Inspection and was						
dete	ermined to be in Airwor	rthy Condition.		FT KK	1		
				Robert R. Kempf	AP573173800IA		
	1 1						
	Carried Control of	1000		1.00	a tella con di		
1							

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10-4-23			894.4	This Engine has been inspected in accordance
				with a 100 hour inspection Compression test Cal # 198
				Cy1 # 2 % Cy1#3 # 80 Cy1# 680 classed gapped His
				SPARK Plugs Vok Changed oil Shell 100 + Squarts Runsage
				alitaked for Leaks Nows found on this Date Reforguid+
	-			Sasty, I act by that this Engine has been inspected in some
				with a 100 hora inspection and was Sound to Bein
				and Alawcathy condition on this Date
				Wholian Smitouse
				In 529862585A+P

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6-18-20	24		896.8	This Engine has been inspected in accountance
				with A 100 hour inspection. Compression TEST COL
-				Accordished with A 100 hour inspection and was
				Sound to be in AN AIRWORTHY condition on This
				date. Wichael Jonis Rauson
_				IA528868595 A+P