

The Standard

The Standard AIRCRAFT LOG

ASA-SA-1


PAIN	T COLOR INFORMATION
N_N14	ORM SN_27-0287
TOP COLOR Graystone	COLOR NO.WP-405_ MFG
ACCENT COLOR_Wine	COLOR NO. HS-10268 MFG
STRIPES Iitanium	COLOR NO. HT-106794FG
воттом wing Dark Blue	COLOR NO. HR-10596MFG

Aircraft Record General	Information		The second second
Manufacturer MOONLY Serial 27-0287 Date of Manufacture 2		Model <u>M20 M</u> Registration Number <u>N14</u>	ORM
Engine(s) currently installed: Manufacturer Ly Comin	S Model IIO-5	540 - AF1B serial L	- 10413-61A
Propeller(s) currently installe	ed:		
Manufacturer McCaud HUB Model B3032C41	7 Serial 99354	Serial	100
		Serial TJ 313	Serial TJ315
Blade Model	Serial	Serial	Serial

Notes
s
е
n see see
y e e
t

YEAR: 2000 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
P	2		1. 12	PRODUCTION FLIGHT TEST COMPLETED THIS
FEB.18	8		4.7	DATE. THIS AIRCRAFT INSPECTED NEW AT
				FACTORY AND FOUND TO BE AIRWORTHY.
				142236
10			h= /b	THIS AIRCRAFT HAS BEEN FLIGHT TESTED
EF-18		-	5.7	IN ACCORDANCE WITH MOONEY AIRCRAFT
				SPECIFICATION 020009 AND FOUND
	4			SATISFACTORY
				FOR FAR ACO ASW 150

YEAR: 2000 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Rep Entries must be endorsed with Name, Rating ar Facility. (See back pages for other specific entries	nd Certificate Number of Technician or Repair
			- 4.00		control of the second
			The state of	4	The 000 Heritaria 0
FEB. 18			5.7		The GPS Navigation System, Make
			77	this Aircraft has been Ground/Flight	this Aircraft has been Ground/Flight
		199	17	tested in accordance with Mooney	tested in accordance with Mooney
				Aircraft Specification 020009, and is approved for use under instrument	Aircraft Specification 020009, and is approved for use under instrument
				Flight Rules, Enroute and Non-	Flight Rules, Enroute and Non-
		521 PM	on Hannah	Precision approaches only.	Precision approaches only.
		7	3)	Signed .	Signed
		de fi	(Mooney Aircraft Corporation	Mooney Aircraft Corporation
		2018/10/14	21-49		
		111-			



R:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician & Repair Facility. (See back pages for other specific entries.)
	25 F	ebruary :	2001 Tac	ARAPAHOE AERO TOWER ROAD ENGLEWOOD, COLORADO 80112 (303) 799-8386 th: 130.0 N140RM Mooney M20M S/N: 27-0287 craft batteries. Michael Nigro A&P 470942287

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE				ests, Repairs a Rating and Certif		rechnician or Repair
DATE	+				ARAPAHO	E AEI	RO		
	1276	0 EAST (CONTROL	TOWER R	OAD ENGLE	WOOD,	COLORADO	80112 (303) 7	99-8386
	N140	RM	MOON	EY	M20M	S	/N: 27-0287	Total T	Time: 134.7
	5 March	h 2001	Tach:	134.7					
	100 Ho	ur / Annu	ial inspection	on complet	ted this date us	sing the l	Mooney M20N	M inspection for	form as a guide.
	Tested I	ELT per F	AR 91.207	(d). ELT I	battery expire	s Januar	ry 2002. Clear	ned and reseale	ed fuel strainer.
	Serviced	and char	ged batterie	s. Lubed la	anding gear and	flight co	ontrol system.	Serviced brak	e reservoir with
	hydrauli	c fluid. Ja	cked aircraf	it and perfo	ormed 5 fault f	ree retrac	ctions and exte	ensions. Check	ed landing gear
	tensions	, lights, a	and warning	horn. Rig	gged landing	gear IAV	W M20M serv	vice manual.	Calibrated both
	digital f	uel quant	ity gauges.	Adjusted a	alternate air li	ght micr	o switch. Clea	aned, neutraliz	zed and painted
	battery b	oox for #	2 battery. T	ightened lo	ower aileron p	ivot hard	ware. Repositi	ioned adel clar	mp next to gear
	actuator	Tighten	ed left inner	flap hard	lware. Secured	wiring	in outer wing	s as required.	Tightened and
	saftied p	ilots yok	e hardware.	Removed	Shadin mini-	flow and	sent for repair	ir and reinstall	led after repair.
	C/W M	ooney S	B M20-276	by inspe	cting overhea	d panel	switches and	installing wir	re loom around
	tubular :	structure.	Mooney S/	B M20-27	5 previously	complied	with at facto	ry. KFC 225	removed from
	aircraft	and sent	for modifica	ation per N	Mooney S/B N	120-277.	. Cleaned win	dows and vac	uumed interior.
	AD's c	hecked tl	hrough bi-v	veekly 200	01-03. I CEI	RTIFY	THAT THIS	AIRCRAFT	T HAS BEEN
	INSPEC	CTED IN	ACCORD	ANCE WI	ITH AN ANN	UAL IN	SPECTION	AND WAS D	ETERMINED
	TO BE	IN AN A	IRWORTH	Y CONDI	ITION.				
		cal	16		M	ichael Ni	igro A&P 470	0942287 IA	w/o 17264

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
650		Tubility (Coo busin pages to cartar operation strainer)
		* * * * * * * * * * * * * * * * * * * *
		Installation Bulletin 472 Alert Effective Date 1/01.
		Complied this date In Accordance With Honeywell IB #472 Alert Rev 1 Jan/01. This KC-225 Autopilo computer was returned to the Honeywell factory for compliance to this bulletin. Affected unit:
		KC-225 PN <u>O65-00183-0361</u> S/N <u>1514</u> A/P was tested per Honeywell manual # <u>006-1655-7-003</u> Static sytem was retested per FAR 43 apdx E. Details of file under J.O. # <u>29645</u>
		Sign
	TACH	TACH FLIGHT

FAA A	CROWNAIR Approved Repair Station	#CWNR273K	· Rep
<u> </u>	3753 John J. Montgom		
_	San Diego, CA 92	Participation of the Control of the	
Reg. #. N140RM	Model: M20M	S/N: 27-0287	-
Date: March 8, 2002	Hobbs: 236.8	Total Time: 236.8	
	그렇게 뭐하다 하다 하나 아니는 그 집에 없는 그 얼마나 있다면 하는 것이 없었다면 하는 것이 없어요. 그렇게 되었다면 하는 것이 없다면 하는데 하는데 없다면 하는데 없	on in accordance with FAR 91.207 (d) March 8, 2008. Replaced fuel cap of	
	그렇게 뭐하다 하다 하나 아니는 그 집에 없는 그 얼마나 있다면 하는 것이 없었다면 하는 것이 없어요. 그렇게 되었다면 하는 것이 없다면 하는데 하는데 없다면 하는데 없	보이 있는 이 용어가는 아무슨 바로 아무슨 아무는 것이 없다면 하는데 얼마나 되었다. 그런 그는 사람들이 살아 있는데 아무를 살아 보고 있다면 하는데 그렇게 하는데 그렇게 되었다.	
	battery replaced due again	March 8, 2008. Replaced fuel cap o	
and found to be in compliance, rings. Adjusted gear tensions to	battery replaced due again proper specifications. Re en inspected in accordance	March 8, 2008. Replaced fuel cap of eplaced vacuum regulator filter, with an Annual Inspection and has	
and found to be in compliance, rings. Adjusted gear tensions to I certify that this aircraft has been been determined to be in airwor	battery replaced due again proper specifications. Re en inspected in accordance thy condition. Pertinent de	March 8, 2008. Replaced fuel cap of eplaced vacuum regulator filter,	
and found to be in compliance, rings. Adjusted gear tensions to	battery replaced due again proper specifications. Re en inspected in accordance thy condition. Pertinent de	March 8, 2008. Replaced fuel cap of eplaced vacuum regulator filter, with an Annual Inspection and has	
and found to be in compliance, rings. Adjusted gear tensions to I certify that this aircraft has been been determined to be in airwor	battery replaced due again proper specifications. Re en inspected in accordance thy condition. Pertinent de	March 8, 2008. Replaced fuel cap of eplaced vacuum regulator filter, with an Annual Inspection and has	

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries n	ption of Inspections, Tests, Repairs and Alterations nust be endorsed with Name, Rating and Certificate Number of Technician or Rep (See back pages for other specific entries.)
- 11	LOG ID# 952	a CROWN, 12-March /N 27-0287	1-2002 REF	# AR-02-16	ntgomery Drive San Diego, CA 92123 CWNR273K 664 HOBBS 236.8 M
s y	certify that ystem tests ave been per as been test	required b formed. Th	by FAR 91.41 ne altimeter	1	The ATC transponder tests and inspections required by FAR 91.413 were performed this date and found to comply with FAR 43 Appendix F.
A	ltimeter SN:	30115			Transponder KT76C SN: 9592
ar	nd is approve	ed for ret	urn to serv	nce. Pert	d inspected in accordance with current FAA regulations inent details of the repair are on file at this Repair
3	KILLA LA	LHay	Λ Λ		-12-02
51	gned CWNR27	3K RUSSE	LL HAYS		ate

	FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123	Repa
_	Reg. # N140RM Model: M20M S/N: 27-0287	
_	Reg. #. N140RM Model: M20M S/N: 27-0287 Date: March 21, 2003 Hobbs: 312.8 Total Time: 312.8	_
-	Completed Annual Inspection. Performed ELT inspection in accordance with FAR 91.207 (d) and found to be in compliance, battery replaced due again March 8, 2008. Replaced fuel cap o-	
=	rings. Adjusted gear tensions to proper specifications. Replaced vacuum regulator filter. CW Parker SL 54 on stand-by vacuum pump, good at this time. CW Mooney SB M20-279 on gear actuator. CW Mooney SB M20-280 gear rod-ends replaced and drilled. Oxygen bottle removed for hydro-static test and reinstalled. Replaced left main tire. Greased all wheel bearings.	

	CROWNAIR	
FAA AI	pproved Repair Station #	CWNR273K
	3753 John J. Montgomer	
	San Diego, CA 92123	
Reg. #. N140RM	Model: M20M	S/N: 27-0287
Date: February 17, 2004	Hobbs: 381.3	Total Time: 381.3
and found to be in compliance, ba el cap o-rings. Replaced vacuum	attery replaced due again N regulator filter. Replaced	farch 8, 2008. Replaced fu right main tire. CW Mooney SB
and found to be in compliance, be	attery replaced due again N regulator filter. Replaced	right main tire. CW Mooney SB
and found to be in compliance, be el cap o-rings. Replaced vacuum M20-282, no back clutch spring I certify that this aircraft has been	attery replaced due again Not regulator filter. Replaced replaced. Serviced both batter inspected in accordance was condition. Pertinent details	farch 8, 2008. Replaced fu right main tire. CW Mooney SB

YEAR:	RECORDING TODAY'S TOTAL	Description of Inspections, Tests	, Repairs and Alterations	or Denois
		CROWNAIR		or Repair
DA.	FAA A	pproved Repair Station #CWNR	273K	
		3753 John J. Montgomery Dr.		
_		San Diego, CA 92123		
	eg.#N140RM Date: December 10, 2004	Model: M20M Hobbs: 428.8	S/N: 1067	
In		CW AD 2004-23-17 by installing Replaced fuel cap o-rings. Replaced		
— — T	he aircraft identified above was	repaired and inspected in accordant proved for return to service. Pertinork Order # LT-04-02397	nce with current Federal nent details of the repair are on	_
		Authorized	d Representative	

		OD OHING TO	
5		CROWNAIR	
	FAA App	proved Repair Station #	CWNR273K
		753 John J. Montgome	
		San Diego, CA 9212	
		our Diego, en 7212	
Reg. #. N140	RM	Model: M20M	S/N: 27-0287
Date: Appril	3, 2005	Hobbs: 433.3	Total Time: 433.3
servo to clear c	able.	eplaced wing walk mate	rial. Repositioned cable guard on roll
servo to clear c			
	is aircraft has been i	nonceted in accordance	
I certify that th	is aircraft has been i	nspected in accordance	with an Annual Inspection and has
I certify that the	d to be in airworthy	condition. Pertinent det	with an Annual Inspection and has ails of the repair are on file at this
I certify that the	is aircraft has been in d to be in airworthy nder Work Order # I	condition. Pertinent det	with an Annual Inspection and has ails of the repair are on file at this
I certify that the	d to be in airworthy	condition. Pertinent det	with an Annual Inspection and has ails of the repair are on file at this
I certify that the	d to be in airworthy	condition. Pertinent det LT-05-02508.	ails of the repair are on file at this atthorized Representative

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	-		1	

Air 88 Inc. dba CROWNAIR 3753 John J. Montgomery Drive San Diego, CA 92123 CWNR273K LOG ID# 1461 04-April-2005 REF# AR-05-3047 HOBBS 433.4 N140RM S/N 27-0287 MOONEY M20M

Pg 1/1

I certify that the altimeter and static system tests required by FAR 91.411 have been performed. The altimeter has been tested to 20,000 feet. The ATC transponder tests and inspections required by FAR 91.413 were performed this date and found to comply with FAR 43 Appendix F.

Altimeter SN: 30115

Transponder KT-76C SN: 9592

The items identified above were repaired and inspected in accordance with current FAA regulations and is approved for return to service. Pertinent details of the repair are on file at this Repair station under work order #AR-05-03047.

Light CWNR273K DALE BARKWILL Date

YEAR:	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections Entries must be endersed with N CROWNAIR	s, Tests, Repairs and Alterations	n or Repair
		F	AA Appro	oved Repair Station #CWI	NR273K	- 10
				3 John J. Montgomery Dr		
			A. 2. 2.	San Diego, CA 92123		
				our origin, our vices		
Reg.#	N140RM			Model: M20M	S/N: 1067	
_	October 12,	2005		Hobbs: 482.1		
Remo	ved fuel stra	iner clea	ned inspec	ted and reinsralled. Lubed	control services.	
Aviati	on Regulation	ons and v	was approv	Order # LT-05-02625.	rtinent details of the repair are on	
				Authori	zed Representative	
	T 1	- 1	- 1			

DATI	CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr.	or Repair
_	San Diego, CA 92123	
_	Reg. #. N140RM Model: M20M S/N: 27-0287 Date: April 19, 2006 Hobbs: 504.3 Total Time: 504.3	
	Completed Annual Inspection. Performed ELT inspection in accordance with FAR 91.207 (d) and found to be in compliance, battery replaced due again April 2007. Replaced fuel cap orings. Replaced all main landing gear shock discs. Removed oxgen bottle for hydrostatic test and reinstalled. Repaced bearing and race in nose gear wheel. Greased all wheel bearings. Serviced both batteries.	
	I certify that this aircraft has been inspected in accordance with an Annual Inspection and has been determined to be in airworthy condition. Pertinent details of the repair are on file at this repair station under Work Order # LT-06-02924. Authorized Representative	

YEAR:	CROWNAIR	JIAT'					
	FAA Approved Repair Station #CWNR273K	lepair					
DATE	3753 John J. Montgomery Dr.	-200					
	San Diego, CA 92123						
	Reg. #. N140RM Model: M20M S/N: 27-0287						
	Date: April 27, 2007 Hobbs: 560.0 Total Time: 560.4						
	Completed Annual Inspection. Performed ELT inspection in accordance with FAR 91.207 (d) and found to be in compliance, battery replaced due again April 2008. Replaced fuel cap orings.						
_	I certify that this aircraft has been inspected in accordance with an Annual Inspection and has been determined to be in airworthy condition. Pertinent details of the repair are on file at this repair station under Work Order # LT-07-03355.						
	Authorized Representative						

_		Air 88 Inc. dba	CROWNAIR			
Y	FAA Ap	proved Repair S	tation #CWNI	R273K		
-	3	3753 John J. Mo	ntgomery Dr.			lepair
4		San Diego, C				
_		Model: Moone	v M20M	SN:	27-0287	
	Reg. #: N140RM	Hobbs Time: 56		WO#:	AR-07-04333	
-	Date: 04/26//07	Hobbs Time. 30	0.2	11 0		
-	I certify that the altimeter and static system test required by FAR 91.411 have been		required by F.	AR 91.413 v	s and inspections were performed	_
_	performed. The altimeter have been tested		this date and	found to con	ply with FAR 43	_
7	to 25,000 feet.		Appendix F.			_
_	Altimeter SN: 30115		Transponder	KT-76C SN	: 9592	-
		and immediate in	accordance with	current Fed	leral Aviation Regulat	ions and
	The aircraft identified above was repaired was approved for return to service. Pertin	ent details of the	repair are on fi	ile at this Re	epair Station under wo	ork order_
-	AR-07-04333,	1				_
_	Ku Corsell	4/26/0	7			_
-	Authorized Representative CWNR	273K Date				_
_	<u>-</u>	k.**				_

.

PATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Entries must be endorsed with Name, Ratin Facility. (See back pages for other specific e	ng and Certificat		r Repair
-			F	Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWN 3753 John J. Montgomery Dr. San Diego, CA 92123	NR273K		
– Da		/08 Airframe		Model: Mooney M20M Hobbs Time: 618.1 ection. Complied with FAR 91.207(D) akes, serviced reservoir. Replaced outer		 27-0287	due
de		e in dirw	orthy condit	spected in accordance with an Airfram ion. Pertinent details of the repair are o			n
A	uthorized Re	presentati	ve	CWNR273K			

YEAR	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Entries must be endorsed with Name, Ratin Facility. (See back pages for other specific e	ng and Certificate Nu	
_			1	Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWN 3753 John J. Montgomery Dr. San Diego, CA 92123	NR273K	
_	Reg. #: N140 Date: 04/30			Model: Mooney M20M Hobbs Time: 618.1	SN:	27-0287
		-		tion. Compressions are as follows: #17 h AD 02-26-01 fuel injector lines inspec		
_ _ _	- /	oe ja airw	orthy condit	spected in accordance with an Engine Attion. Pertinent details of the repair are o		
_	Authorized Re	presentati	ve	CWNR273K		

R'	CROWNAIR						
FAA A	approved Repair Station #0	CWNR273K					
	3753 John J. Montgomery	y Dr.					
San Diego, CA 92123							
Reg. #. N140RM	Model: M20M	S/N: 27-0287					
Date: March 27, 2009	Hobbs: 646.3	Total Time: 646.3					
races and bearings. Replaced th							
	I certify that this aircraft has been inspected in accordance with an Annual Inspection and h						
repair station under Work Order	- 11	ils of the repair are on file at this					
repair station under work order	r # LT-09-04104.	\ \ /					
repair station under work Order	r # LT-09-04104.						
repair station under work Order		morized Representative					

以外の発力を対象をはながりまませた。ませからとう。

YEAR:	RECORDING	TODAY'S	TOTAL	Description of Inspections, Tests,	Repairs and	Alteration	ons
				Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWN 3753 John J. Montgomery Dr. San Diego, CA 92123	R273K		
	eg. #: N1401 ate: 06/30			Model: Mooney M20M Hobbs Time: 657.1		SN:	27-0287
Re	eplaced both	main tires					
was	s approved for	ntified abo or return to	ve was re service.	epaired and inspected in accordance with or Pertinent details of the repair are on file	current Fed at this Repa	eral Avia ir Station	tion Regulations and under work order
_	-09\04282.	1/2 L	\wedge				
Αι	ithorized Rep	presentativ	re	CWNR273K			

AIR 88 Inc. dba CROWNAIR AVIATION FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

N140RM 4/07/2010 MOONEY M20M HOBBS: 705.8

S/N: 27-0287

I certify that the altimeter(s) and static system test required by FAR 91.411 have been performed and and found to comply with FAR 43 Appendix E. The altimeter(s) have been tested to 25,000 feet. I certify that the ATC transponder(s) test and inspection required by FAR 91.413 has been performed and found to comply with FAR 43 Appendix F.

Pilot altimeter - King KEA130 S/N: 30115 Encoder - King KEA130 S/N: 30115 Transponder- KT76C S/N: 9592

While performing static and pitot system test found excessive leaks by autopilot connections and pitot tube connection respectively. Repaired leaks and retested static and pitot system. Checked OK. All work done in accordance with current FARs.

The aircraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this agency under Work Order No. LT-10-04651.

Authorized Representative

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair
ATE				Facility. (See back pages for other specific entries.)
-				
				Air 88 Inc. dba CROWNAIR
			FA	A Approved Repair Station #CWNR273K
				3753 John J. Montgomery Dr.
				San Diego, CA 92123
	11.40014	1.77	45	
	N140RM			MOONEY M20M S/N: 27-0287
1 2	1/07/2010			HOBBS: 705.8
N	Maintenance			I/A/IV/ Crownein 100 Hour/Annual Inspection Checklist, Form CA 105
-				I/A/W Crownair 100 Hour/Annual Inspection Checklist, Form CA 105.
-				test and inspection, batteries due 4/2012
- 13				with new P/N: CV1J4
- 1	Replaced	1	dum micro	
				CONTROLLES
	_			

- Replaced inside/outside, right/left fuel cap O rings - Serviced #1 and #2 aircraft batteries - Replaced vacuum regulator filter with new P/N: B3-5-1 I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition. I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order #LT-10- 04651 Authorized Representative	TIME TIME FLIGHT TIME IN SERVICE Entries must be endorsed with Name, Rating and Certificate Number of Facility (See back pages for other specific entries.)		Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs (See back pages for other specific entries.)		
- Serviced #1 and #2 aircraft batteries - Replaced vacuum regulator filter with new P/N: B3-5-1 I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition. I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order #LT-10-04651	DATE	-			r domy. (See back pages for other specific entires.)
- Replaced vacuum regulator filter with new P/N: B3-5-1 I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition. I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order #LT-10-04651	-	Replaced ins	ide/outsic	de, right/left	fuel cap O rings
I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition. I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order #LT-10-04651	-	Serviced #1	and #2 air	rcraft batteri	ies
I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order #LT-10-04651	-	Replaced va	cuum regi	ulator filter	with new P/N: B3-5-1
	I ceracco	rworthy con- rtify that on ordance with	dition. ly the wo	ork requeste	ed by the owner/operator and listed above was repaired and inspected in tion Regulations and was found to be airworthy for return to service. Details under Work Order #LT-10- 04651
		-			
	_	-			

	Air 88 Inc. dba CROWNAII	t	î
2	FAA Approved Repair Station #CW	NR273K	-
	3753 John J. Montgomery D		
-	San Diego, CA 92123		
-			-
N140RM	MOONEY M20M	S/N: 27-0287	_
7-7-2010	HOBBS: 721.4		i
Maintenance performed:			-
- Replaced right inner of	loor link with new P/N: 550082-501		
-			-
I certify that this aircraft airworthy condition.	ft has been inspected in accordance with cu	rrent FARs and was determined to be in	١ -
-			-
	ork requested by the owner/operator and listederal Aviation Regulations and was found to be	경영하다 하다 마다 가지 않는데 그렇게 하다 나를 가입하다 하는데 하다 하는데 하다 하나 하다 하는데 하는데 하는데 하다 하는데 하는데 하다 하는데 하다 하는데	
the repair are on file at this	s agency under Work Order #LT-10- 04820		-
_	100	Rober	-

	FAA Approved Repair Station #CW 3753 John J. Montgomery D	NR273K
	San Diego, CA 92123	
N140RM 4-29-2011	MOONEY M20M HOBBS: 757.2	S/N: 27-0287
 Complied with FAR 91.20 Sent out O2 bottle for hyd 01, serviced O2 in full Installed section of rubber 1 Cleaned, inspected and report of the complex of the complex	nose over #3 cylinder oil drain tube.	2012 r and installed new boss seal P/N: 59776-
		CONTINUED
		MEXT. PAGE

- D	in ai	rworthy cor	ndition.	vork reques	nspected in acco	er/operator and	listed above	was repaired a	and inspected in
					y under Work Or		1. A	Representative	0
_									
=	<								

Page 1 of 2

N140RM

Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

5-01-12 Maintenance performed: Mooney M20M

Hobbs: 814.1 Hrs

S/N: 27-0287

ACTT: 814.1 Hrs

- Completed Annual Inspection I/A/W Crownair 100 Hour/Annual Inspection Checklist, Form CA 105.
- Replaced ELT batteries with new Duracell MN1300 D cell batteries. New expiration date: March 2018.
- Complied with annual ELT inspection and functional test I/A/W FAR 91.207(d) and found satisfactory.
- Complied with AD 2012-05-09 (Mooney SB M20-313A) by inspection and found empennage trim fitting
 and attaching hardware are tight and installed correctly. No further action required.
- Installed new Gill G-243 battery, S/N G02717600 after servicing with acid and charging.
- Removed L/H & R/H landing light lenses, cleaned, polished and reinstalled.
- Serviced oxygen system to full as required.
- Replaced R/H landing light outboard lamp with new P/N GE4596. Ops check good.
- Replaced L/H and R/H recognition light assys with new P/N 01-0770303-01. Installed new pins to plugs and secured wiring. Ops check good.

Page 2 of 2

Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

N140RM

Mooney M20M

S/N:

27-0287

5-01-12

Hobbs: 814.1 Hrs

ACTT: 814.1 Hrs

Maintenance performed:

- Repaired holes on L/H & R/H wing tip lenses with clear RTV to seal.
- Replaced vacuum regulator filter with new P/N B3-5-1.

I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order #PA-12-05744.

Authorized Representative

Air 88, Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J Montgomery Dr. San Diego, CA 92123

N140RM 5-01-12 Mooney M20M

S/N: 27-0287

Hobbs: 814.1 Hrs

ACTT: 814.1 Hrs

I certify that the altimeter(s) and static system test required by FAR 91.411 have been performed and found to comply with FAR 43 Appendix E. The altimeter(s) have been tested to 20,000 feet. I certify that the ATC transponder(s) test and inspection required by FAR 91.413 has been performed and found to comply with FAR 43 Appendix F.

Pilot ADC:

S/N 30115

#1 Transponder: S/N 9592

The aircraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this agency under Work Order #PA-12-05744.

Authorized Representative

EAR:	TACH FLIGHT TIME I	N Entries must be endorsed with Name Bating	g and Certificate Number of Technician or Rep
Pag	ge 1 of 2	Air 88 Inc. dba CROWNAIR	
		FAA Approved Repair Station #CWNR2	273K
		3753 John J. Montgomery Dr.	
		San Diego, CA 92123	
N14	40RM	Mooney M20M	S/N: 27-0287
6-0	3-13	Hobbs: 867.2 Hrs	ACTT: 867.2 Hrs
Ma	intenance performed:		
-	Completed Annual Inspect	tion using Crownair Aviation Annual/100	Hour Inspection Checklist, Form CA
	105.		
-	Complied with annual ELT	inspection and functional test I/A/W FA	R 91.207(d) and found satisfactory.
	Batteries expires March 201	8.	500
-	Replaced remote ELT switch	h battery with new P/N 2L76.	
-		ith new P/N MS29513-338 & P/N MS29513	3-010 on both left and right sides.
-	Serviced oxygen system to 2	2000 PSI as required.	
-	Replaced fuel drain hose on	right side with new P/N 193-4.	

YEAR:	TACH FLIGHT		Description of Inspections, Tests, R Entries must be endorsed with Name, Rating	epairs and Alterations and Certificate Number of Technician or Repai
<u> </u>				58_52
_ 1	Page 2 of 2		Air 88 Inc. dba CROWNAIR	
		FA	A Approved Repair Station #CWNR2	273K
-			3753 John J. Montgomery Dr.	
-			San Diego, CA 92123	
- 1	N140RM		Mooney M20M	S/N: 27-0287
. 6	5-03-13		Hobbs: 867.2 Hrs	ACTT: 867.2 Hrs
	certify that this airc		inspected in accordance with an Annual	Inspection and was determined to be
.				
_	나이들은 이 경기를 잃었다면 프랑스 시간이라고 있었다면 그 이번 사람이 있다면서 하는데 하다면 다.		sted by the owner/operator and listed a iation Regulations and was found to be a	
			y under Work Order No. PA-13-06161.	\bigcirc \bigcirc \bigcirc \bigcirc \bigcirc
-				- and
-			Auth	norized Representative
_ L				

1		Description of Inspections, Tests, R	
Page 1	of 2	Air 88 Inc. dba CROWNAIR	
		FAA Approved Repair Station #CWNR2	73K
		3753 John J. Montgomery Dr.	
		San Diego, CA 92123	
N140R	M	Mooney M20M	S/N: 27-0287
6-09-14	1	Hobbs: 906.1 Hrs	ACTT: 906.1 Hrs
Mainte	enance performed:		
- Co	mpleted Annual Inspe-	ction using Crownair Aviation Annual/100 l	Hour Inspection Checklist, Form Ca
10:	7,65		
0.0000000		T inspection and functional test I/A/W FA	R 91.207(d) and found satisfactory
2.555	tteries expires March 20		
fol	lowing components to 2	111 Part 43 Appendix E and FAR 91.413 0,000 feet: Encoding Altimeter P/N 066-030 9592. No defects noted.	
- Re	moved and replaced old	oxygen bottle with overhauled oxygen bott -24055, Mfg. Date: December 2010, Expires:	마이아프라이 아닌 내리 나의 아내는 아이는 나는 것이 되었다. 그런 그 아이를 하는 것이 아니라 아니라 아니라 이 경기에 가지 않는데 아니라

Page 2 of 2	Air 88 Inc. dba CROWNAIR	
	FAA Approved Repair Station #CWNR2	273K
	3753 John J. Montgomery Dr.	
	San Diego, CA 92123	
N140RM	Mooney M20M	S/N: 27-0287
6-09-14	Hobbs: 906.1 Hrs	ACTT: 906.1 Hrs
test due June 2019. Se	rviced oxygen bottle to 2000 PSI and leak check	ced good.
[2] [20] [2] [2] [2] [2] [2] [2] [2] [2] [2] [2	both main tires with new Goodyear Flight Custo 7544 and R/H S/N 31927713 and serviced to 42	
	wick on R/H side of inboard horizontal stabilizer	
I certify that this aircraft ha	as been inspected in accordance with an Annual	I Inspection and was determined to be
in airworthy condition.		
I certify that only the wor	k requested by the owner/operator and listed	above was repaired and inspected in
	leral Aviation Regulations and was found to be a is agency under Work Order No. PA-14-0658	()
	- 1	no VI
	-/ /	// /

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Test Entries must be endorsed with Name, Ra Facility. (See back pages for other specific	ating and Certificate Number of Technician or Rep
Page	1 of 2			Air 88 Inc. dba CROWNAIR	
			FA	A Approved Repair Station #CWNR2	273K
				3753 John J. Montgomery Dr.	
				San Diego, CA 92123	
N140)RM			Mooney M20M	S/N: 27-0287
6-11-	-15			Hobbs: 940.5 Hrs	ACTT: 940.5 Hrs
Mair	atenance perf	ormed:			
-				Crownair Aviation Annual/100 Hour Ins and functional test I/A/W FAR 91.207(spection Checklist, Form CA 105. (d) and found satisfactory. Batteries expires
-	Replaced o-ris	ngs on both	L/H and R/H	I wing fuel caps with new.	
-	Serviced oxyg	en to 1850	PSI.		
				ke linings with new P/N 066-10500.	
				m inop, "Trim Fail" light comes on. In m, "Trim Fail" annunciation extinguished	spected trim servo and connections. After d and all Ops checks were good.

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Entries must be endorsed with Name, Ratin Facility. (See back pages for other specific	ng and Certificate Number	
ATE				, down, (ooo baan pages to outer opening		
Pag	ge 2 of 2		ı	Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR2 3753 John J. Montgomery Dr.	73K	
				San Diego, CA 92123		
NI	40RM			Mooney M20M	S/N:	27-0287
6-1	1-15			Hobbs: 940.5 Hrs	ACTT:	940.5 Hrs
	ertify that this	aircraft h	as been inspe	ected in accordance with an Annual Inspec	etion and was determine	d to be in airworthy
I co	ertify that onl	y the work	requested by	y the owner/operator and listed above was	repaired and inspected service. Details of the	in accordance with repair are on file at
	s agency unde			5-07126.	7800	
				Kut	thorized Representative	

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

Air 88 Inc. dba CROWNAIR
FAA Approved Repair Station #CWNR273K
3753 John J. Montgomery Dr.
San Diego, CA 92123

N140RM

Mooney M20M

S/N: 27-0287

7-27-15

Hobbs: 952.5 Hrs

Maintenance performed:

 Customer reports stall warning horn comes on when master switch is turned on. Removed and replaced stall warning switch with new P/N 800424-9015. Checks good at this time.

I certify that with respect to the work performed this aircraft was repaired and inspected in accordance with current FAA regulations. Only those items specified in the work order have been inspected and found to be airworthy and returned to service. Pertinent details of this repair are on file at this agency under Work Order No. PA-15-07179.

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

Air 88 Inc. dba CROWNAIR
FAA Approved Repair Station #CWNR273K
3753 John J. Montgomery Dr.
San Diego, CA 92123

N140RM

Mooney M20M Hobbs: 962.9 Hrs S/N: 27-0287

11-04-15

Maintenance performed:

Removed and replaced #2 battery with new Gill P/N G243, S/N G02867894, serviced, charged and installed.

I certify that with respect to the work performed this aircraft was repaired and inspected in accordance with current FAA regulations. Only those items specified in the work order have been inspected and found to be airworthy and returned to service. Pertinent details of this repair are on file at this agency under Work Order No. PA-15-07412.

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Test Entries must be endorsed with Name, Ra Facility. (See back pages for other specif	ating and Certificate Number of Technician or Repa
Page	1 of 2		FA	Air 88 Inc. dba CROWNAIR AA Approved Repair Station #CWNR2 3753 John J. Montgomery Dr. San Diego, CA 92123	273K
N140)RM			Mooney M20M	S/N: 27-0287
6-06-	-16			Hobbs: 974.9 Hrs	ACTT: 974.9 Hrs
Mair	tenance perf	formed:			
				Crownair Aviation Annual/100 Hour In	
	Complied wit due March 20		LT inspection	on and functional test I/A/W FAR 91.20	7(d), all checks good at this time. Batteries
					43 Appendix F. Certified the following

- 01156-0101, S/N 9592. No defects noted.
- Removed #1 battery P/N G-243, S/N G02717600 per customer's request. Serviced and charged new battery P/N G-243, S/N G02891545 and installed in #1 position. Secured terminals, installed lid and safety wired.
- Replaced inside and outside o-rings on left and right wing fuel caps with new P/N MS29513-338 & P/N MS29513-010.

ATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Entries must be endorsed with Name, Ration Facility. (See back pages for other specific	ng and Certificate Number of Technician or Repa
Pag	e 2 of 2			Air 88 Inc. dba CROWNAIR	
			F	AA Approved Repair Station #CWNR27	73K
				3753 John J. Montgomery Dr.	
				San Diego, CA 92123	
N14	ORM			Mooney M20M	S/N: 27-0287
6-06	5-16			Hobbs: 974.9 Hrs	ACTT: 974.9 Hrs
-	Bled left and	right brake	es and service	ed reservoir as required.	
-				robe light P/N 01-0770058-13, Model A ght illuminates.	.625-D with new tail strobe light P/N 01-
				= =	
	rtify that this a dition.	ircraft has	s been inspec	ted in accordance with an Annual Inspec	etion and was determined to be in airworthy
curr	ent Federal A	viation Reg	gulations and	was found to be airworthy for return to	repaired and inspected in accordance with service. Details of the repair are on file at
this	agency under	work Ord	er No. PA-10	-0/631.	Authorized Representative

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or	Repair
DATE				Facility. (See back pages for other specific entries.)	
	I	1			
	ALA	F_{\sim}	INC	-	
_	Avionics In	nstrume	nts Electi	onics 1-951-677-0085 CRS# DG3R448L	_
	37610 Sky	Canyon	Drive H	anger 51	_
	Murrieta (CA 9256	3	www.aieinc.com / // Since 1984	
_				N ACO	_
_	ALL WORK BI	ELOW CON	MPLETED BY	AIE, INC. DG3R448L BY CANAL THE WASHED_24JUN2016	_
_	N140RM				
_	SN: 27-0287				_
	TAT: ?				
_	TOTAL CYCL	ES: ?			_
_				and replaced with Honeywell exchange unit KS270C 065-00178-2500 SN: 5174 see AIE, Inc.WO#44752 Dated 24JUN2016.	_
_	**********	*******	*********	NOTHING *FOLLOWS**********************************	_

11,339040

Page 1 of 2

CROWNAIR

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

N140RM

Mooney M20M

S/N:

27-0287

10-17-17

Hobbs: 1033.7 Hrs

ACTT:

1033.7 Hrs

Maintenance performed:

- Completed Annual Inspection using Crownair Aviation Annual/100 Hour Inspection Checklist, Form CA 105.
 Researched ADs through bi-weekly issue of this date, all ADs are in compliance at this time.
- Complied with annual ELT inspection and functional test I/A/W FAR 91.207(d) and found satisfactory. Batteries expires
 October 2019.
- Replaced o-rings on both L/H and R/H wing fuel caps with new P/N MS29513-338 and MS29513-010.
- Serviced oxygen to 2000 PSI.
- Removed and replaced both Left and Right burned out landing light with new P/N GE 4596. Adjusted landing lights and ops check good.
- Removed and replaced instrument air filter with new P/N AAD9-18-1.
- Removed and replaced vacuum regulator filter with new P/N ARB3-5-1.
- Removed and replaced vacuum in-line filter with new P/N AA2J4-6.

Page 2 of 2

CROWNAIR

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

N140RM

Mooney M20M

S/N:

27-0287

10-17-17

Hobbs: 1033.7 Hrs

ACTT:

1033.7 Hrs

 Removed nose wheel and disassembled. Cleaned and inspected wheel halves with no discrepancies noted. Installed new tire P/N 070-312-0 S/N 7072S00066 with original tube and reassembled. Reinstalled to aircraft with new cotter key, serviced tire to 49psi.

I certify that this aircraft has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-17-08124.

4.1100

AR:	TACH FLIGHT TIME I	IN Entries must be endorsed with Name Bat	ing and Certificate Number of Technician or Rep
Pag	e 1 of 2	CROWNAIR	
	,	FAA Approved Repair Station #CWNR2	73K
		3753 John J. Montgomery Dr.	
		San Diego, CA 92123	
N14	40RM	Mooney M20M	S/N: 27-0287
11-0	05-18	Hobbs: 1070.0 Hrs	ACTT: 1070.0 Hrs
Ma	intenance performed:		
-		using Crownair Aviation Annual/100 Hour Ins	
	Complied with annual ELT ins due JAN 2025.	spection and functional test I/A/W FAR 91.207	7(d), all checks good at this time. Batteries
-		Part 43 Appendix E and FAR 91.413 Part Pilot's Encoding Altimeter P/N 066-03064-000	
	01156-0101, S/N 9592. No det		05. 5/N 50115. and Transponder P/N 000
	Serviced #1 and #2 battery cell	levels as required.	
-	Cleaned, inspected and greased	[전 [2] 5 [1] - (1) - (1	
		sings on lott and sinks when first some with some	P/N MS29513-338 & P/N MS29513-010.

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests Entries must be endorsed with Name. Rate	ting and Certificate Number of Technician or Roo
Page	2 of 2			CROWNAIR	
			FA	A Approved Repair Station #CWNR2	73K
				3753 John J. Montgomery Dr.	
				San Diego, CA 92123	
N140	0RM			Mooney M20M	S/N: 27-0287
11-0				Hobbs: 1070.0 Hrs	ACTT: 1070.0 Hrs
-					with all new main gear shock discs P/N J-
	tify that this a	ircraft has	s been inspec	ted in accordance with an Annual Inspec	ction and was determined to be in airworthy
					s repaired and inspected in accordance with
	ent Federal A agency under				service. Details of the repair are on file a
					Authorized Representative

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Facility. (See back pages for other specific entries.)	
	Airtronics LOG ID# 6 N140RM	12380 Ai 22 06-De S/N 27-0	cember-2019	Hanger 6 Martell, CA 95642-9521 TH3R867L 9 WO# 412 DNEY M20M	Pg 1 / 1
	CORRECTIVE 1) REMOVED INSTALLED A PILOTS AVIO FEDERAL AVI 190-00734-1 COMPLY WITH 2) THE TRAN REQUIREMENT	ACTION: KT76C TRAN ADSB COMPL DNICS PANE IATION REG 10, Rev 13 H FAR 91.2 NSPONDER T	SPOMDER P/N IANT TRANSP L IN ACCORD ULATIONS AN , August 31 27.		01 IN
	lul	//w	MADE IAW F	FEDERAL AVIATION REGULATIONS AND FOUND TO BE AIRWORTHY. 7 / 9 / 19 Date	

YEAR:	TOTAL TIME IN SERVICE		Major Repairs and Major 37 by Date, or to the Work Or			
DATE						
			GOLD WING AVIATION			
		Gold Wing	An AIRTRONICS INC. company	REG; N 140RM	WO#: 461	
		Aviation	12380 Airport Road, Hangar 6 Jackson, CA 95642 209-418-0004	MAKE: MOONEY	MODEL: M20M	
		LOCATION: INSPECTION		S/N: 27-0287		
		SERVICE DESCRIPTION		AFTT: 1116.50	TACH: 1116.50	
- 1		serviced. Oxygen system 6) Serviced #1 and #2 ba	O2 bottle for hydrostatic test, re-installed oxyg labeled inop until service is performed. ttery cell levels as required. med above was done in Accordance With (IAV		be filled and checked for leaks when	-
		I certify this airframe (S/N	med above was done in Accordance With (IAV i 27-0287) has been inspected IAW an annual rational run of engine and controls IAW 43.15(inspection, IAW FAR 43 App		
		I certify this aircraft has b	een inspected IAW a 12 menth ELT inspection Battery Replacement Key Due: December, 09	, IAW FAR 91.207 par. (d) a	***************************************	
		1				
		CERT: A&P 3854194				
	_	AND 3034 194				

TOTAL TIME IN SERVICE		rence of Major Repairs and form ACA-337 by Date, or to the	10 Part 10 10 Part 10		ne Approving Agency	
Gold		GOLD WING AVIATION An AIRTRONICS INC. company	REG: N 140RM	WO#:	719	
Aviatio	n	12380 Airport Road, Hangar 6 Jackson, CA 95642 209-418-0004	MAKE: MOONEY	MODEL:	M20M	
LOCATION: "			S/N: 27-0287			
LOCATION: II			AFTT: 1189.00	TACH:	1189.00	
SERVICE DES	RIPTION:					
 installed new parts) installed new Flig Removed, cleare 	al wing walk tape at Special II 6.00-6 f, inspected and n al lubrication of all	m screw on RH upper wing root, Sealed with PR1422-B-10 on RH wing leading edge. I tree on LH and RH main wheels. e greased all wheel bearings with Aeroshell 5 grease. I components in lubrication guide for 100hr service with spe wing.				
All applicable AD's a	re in compliance a	I this time.				
The following work p	erformed above w	as done in Accordance With (IAW) Mooney M20M MM				
controls IAW 43.15((S/N 27-0287) has)(2), and found to	s been inspected IAW an annual inspection, IAW FAR 43 A be airworthy. Next due 1 March , 2022	pp. D and was determined to be airwo	rthy at this time. P	erformed operational run of engine and	
I certify this aircraft to Due December, 09		IAW a 12 month ELT inspection, IAW FAR 91 207 par. (d)	and was determined to be airworthy.	Next due Febuery	90, 2022 Battery Replacement Next	
1/2	1					
MANNE: RAND	ZIEMER	RTS DATE: Febuary 07, 2021				

Airtronics 12380 Airport Road Hanger 6 Martell, CA 95642-9521 TH3R867L LOG ID# 737 28-October-2020 WO# 686 N140RM S/N 27-0287 MOONEY M20M TACH 1175.1 Pg 1/1 REMOVED: GARMIN GNS 430, P/N: 011-00280-00, S/N: 96305524. INSTALLED:A GARMIN GTN650XI, P/N: 011-04631-00, S/N: 5FP001764 IN THE PILOTS PANEL. INSTALLATION(S) WERE CARRIED OUT IAW APPROVED IMS, AND STCS. THE AIRCRAFT IS LISTED ON THE STCS APPROVED AML(S). FULL DETAILS OF THE INSTALLATIONS CAN BE FOUND ON FAA 337 FILED THIS DATE FOR MAJOR ALTERATIONS. THE CURRENT WEIGHT AND BALANCE WAS NEGLIGIBLE AND EQUIPMENT LIST HAS BEEN REVISED AND PROVIDED. THE ABOVE WORK WAS CARRIED OUT IAW FEDERAL AVIATION REGULATIONS, AND FOUND TO BE AIRWORTHY.	YEAR:	TOTAL TIME IN SERVICE	Reference of Major Repairs and Major Alterations To FAA Form ACA-337 by Date, or to the Work Order by Number and the Approving Agency
LOG ID# 737 28-October-2020 WO# 686 N140RM S/N 27-0287 MOONEY M20M TACH 1175.1 REMOVED: GARMIN GNS 430, P/N: 011-00280-00, S/N: 96305524. INSTALLED:A GARMIN GTN650XI, P/N: 011-04631-00, S/N: 5FP001764 IN THE PILOTS PANEL. INSTALLATION(S) WERE CARRIED OUT IAW APPROVED IMS, AND STCS. THE AIRCRAFT IS LISTED ON THE STCS APPROVED AML(S). FULL DETAILS OF THE INSTALLATIONS CAN BE FOUND ON FAA 337 FILED THIS DATE FOR MAJOR ALTERATIONS. THE CURRENT WEIGHT AND BALANCE WAS NEGLIGIBLE AND EQUIPMENT LIST HAS BEEN REVISED AND PROVIDED. THE ABOVE WORK WAS CARRIED OUT IAW FEDERAL AVIATION REGULATIONS, AND FOUND TO BE AIRWORTHY.	DATE		
INSTALLED:A GARMIN GTN650XI, P/N: 011-04631-00, S/N: 5FP001764 IN THE PILOTS PANEL. INSTALLATION(S) WERE CARRIED OUT IAW APPROVED IMS, AND STCS. THE AIRCRAFT IS LISTED ON THE STCS APPROVED AML(S). FULL DETAILS OF THE INSTALLATIONS CAN BE FOUND ON FAA 337 FILED THIS DATE FOR MAJOR ALTERATIONS. THE CURRENT WEIGHT AND BALANCE WAS NEGLIGIBLE AND EQUIPMENT LIST HAS BEEN REVISED AND PROVIDED. THE ABOVE WORK WAS CARRIED OUT IAW FEDERAL AVIATION REGULATIONS, AND FOUND TO BE AIRWORTHY.		LOG ID# 737	28-October-2020 WO# 686
THE ABOVE WORK WAS CARRIED OUT IAW FEDERAL AVIATION REGULATIONS, AND FOUND TO BE AIRWORTHY.		INSTALLED:A O WERE CARRIED FULL DETAILS	GARMIN GTN650XI, P/N: 011-04631-00, S/N: 5FP001764 IN THE PILOTS PANEL. INSTALLATION(S) OUT IAW APPROVED IMS, AND STCS. THE AIRCRAFT IS LISTED ON THE STCS APPROVED AML(S). OF THE INSTALLATIONS CAN BE FOUND ON FAA 337 FILED THIS DATE FOR MAJOR ALTERATIONS.
- Signed TH3R867L JASON KUBIAK Date		THE ABOVE WOL	RK WAS CARRIED OUT IAW FEDERAL AVIATION REGULATIONS, AND FOUND TO BE AIRWORTHY. $11/4/20$

STORE BY BUTCH THE WATER BY

R:	A.D. NUMBER	TOTAL TIME IN SERVICE	Airworthiness Directives Chronological Listing of Compliance and Method of Compliance	300
			ort Road Hanger 6 Martell, CA 95642-9521 TH3R867L lary-2021 WO# 719 HOBBS 1189.1 MOONEY M20M	Pg 1 / 1
	DISCREPANCY	: 1) REPLAC	E ATTITUDE INDICATOR AND REPLACE HSI 2) 91.411 TESTING.	
	GI-275 CER PILOTS PANE THE STCS A FOR MAJOR	TIFIED AI, L. INSTALLA PPROVED AML ALTERATIONS 14 CFR 91.	REMOVEDKI-525A, KI-526, KMT-112, KG-102A AND VACUUM SYSTEM. P/N: 011-04489-00, S/N:5MZ201129 AND CERTIFIED HSI, S/N:5MZ FION(S) WERE CARRIED OUT IAW APPROVED IMS, AND STCS. THE AIR (S). FULL DETAILS OF THE INSTALLATIONS CAN BE FOUND ON FAA. 2) THE ALTIMETER AND ALTITUDE REPORTING EQUIPMENT HAVE BE 411, AND FOUND TO MEET THE REQUIREMENTS OF PART 43 APPENDIX	2001148 IN THE ERCRAFT IS LISTED ON 337 FILED THIS DATE SEN TESTED AS
	THE ABOVE A	LTERATIONS I	WERE CARRIED OUT IAW APPROVED IM'S AND FEDERAL AVIATION REC	GULATIONS AND FOUND
	110	W	En 2/8/21	
,	signed TH3	R867L JASO	N KUBİAK Date	
Ī				

Savage Aviation, LLC 20511 Skywest DR

Airframe

20511 Skywest DR Date
Hayward CA 94541 09/28/2021

N140RM Make: Mooney Model: M20M S/N 27-0281 Hobbs: 1202.7 TT: 1202.7

Removed and replaced all landing and taxy lights with LED lights P/N P36P2L X2 and P/N P36P2T X2 using existing wiring and mount brackets. Removed wing tip nav and strobe lights and installed LED unit P/N 01-0790725-11, 010790725-12 in existing light mount, using existing wiring harness. LED taxy, landing, and nav/strobe light installation considered a miner alteration.

Work performed in accordance with applicable maintenance manuals. Operations and/or leak check performed for work performed.

Work limited to what is stated above

Daniel Umanzor AP3776498

e avag	e otviation,	££C 20511 Skywest DR	Date
Airframe		Hayward CA 94541	02/24/2022
N140RM Ma	ke: Mooney Model: M20	DM S/N 27-0281 Hobbs: 1253.4 TT	: 1253.4
Found rod end ja gears. Removed a Work performed	m nut on left main gear actuator ro and replaced both main gear brake in accordance with applicable ma	intenance manuals. Operations and/or leak che	wn lock values on all 3
performed.	Work minited to		zor AP3776498
The state of the s	요즘 아내가 가게 가게 되어 하다 하나 아내가 하나 하나 하나 하는 것이 없는데 얼마나 되었다면 하는데 되었다. 그렇지 않는데 얼마나 하나	what is stated above	

Savage Aviation, LLC 20511 Skywest DR

Airframe

Date Hayward CA 94541 02/24/2022

N140RM Make: Mooney Model: M20M S/N 27-0281 Hobbs: 1253.4 TT: 1253.4

Aircraft Annual inspection performed in accordance with scope and detail of 43.13 appendix D. Preformed visual inspection of aircrafts outer skins and accessible inner structures. Cleaned inspected and lubricated flight controls, engine controls, landing gear, and corresponding linkages and or pulleys. Inspected electrical installations and components for security of installation and chafing. Fuel system filters removed inspected and cleaned. Performed gear retraction and extension test. Performed 5X normal and 3X emergency gear extensions. No discrepancies noted at this time, service brake reservoir with MILL5606 fluid. Removed and replaced following components with new, induction air filter ED04028. FAR91.207(D) ELT test complied by visual, and operations test, no discrepancies noted ELT battery replacement Due 3-2023, AD list updated and added to aircraft records. Work performed in accordance with Moony M20M maintenance manuals

I Certify that this aircraft has been inspected in accordance with FAR 43 Appendix D (Annual) inspection and is in an airworthy condition at this time.

Evan Sather AP3233776IA

(snc)

ional

anal

Ti⇒XTRON Lycoming

N140RM #1

ENGINE LOG

- CLOSED -

SSP-1872-1

TEXTRON Lycoming

SIN 27-0287

652 Oliver Street
Williamsport, PA 17701 U.S.A.
570/323-6181
CRANKSHAFT.

ENGINE LOG DER CAROL OF AND MAINTENANCE RECORD 570 327-7048

RECORD OF	TEXTRON LYCOMING			TIO-540-AF1B			L-10413-61A	
		MAKE			MODEL		SERIAL	
FROM				19	то _			19
DETAILING TI	ME FROM	_		HOURS		то _		
INS	TALLED	IN	N 00 N	HOURS	MOGI		HOURS	3
SSP 1872-	.1		C 1994 by To	extron Lycoming "/	All Rights Reserved"		Octo	ber 1994

RIN: NI40RM

NEW RECIPROCATING ENGINE CERTIFICATE

This is to certify that the engine as described hereinafter has been manufactured run-in and tested as prescribed by TEXTRON LYCOMING specifications and Federal Aviation Regulations. No further run-in is required. All applicable Federal Aviation Administration Directives and Textron Lycoming Service Bulletins have been complied with at time of Manufacture.

MODEL TIO-540-AF1B SERIAL NO

L-10413-61A

AUTHORIZED REPRESENTATIVE

TEXTRON Lycoming

652 Oliver Street Williamsport, PA 17701 U.S.A.

ENGINE DESCRIPTION

Mfgr. TEXTRON LYCOMING	Place Williamsport, PA	17701 Date	
Туре	Model	Serial No.	
Rated H.P.	Max. H.P.	Weight (Dry)	
Rated R.P.M.	Max. R.P.M.	Oil Pressure	
Bore	Stroke	Displacement	Cu. In.
Compression Ratio	Supercharger Ratio		
Reduction Gear Ratio			
Propeller	Hub Design	Hub Serial No.	
Blade Design	Blade Serial No.	Blade Serial No.	
Max. Hub H.P.	Max. Blade H.P.		
Pitch	Diameter	Length	
Name			
Address			

Serial No.

MARCH 2000 Ho	yeoming TIO-540-AF1B s/n: L-10413-61A TT: 21.4 bbs: 0021.4	
talled new rate controller, I	P/N LW-10098, S/N BGN 15782, using new gasket and O-rings. Fli	ght che
FAA FORM 8130-3	AIRWORTHINESS APPROVAL TAG User / Installer Responsibilities	
Where the user/installer Authority different than tessential that the user/in components/assemblies	and that the existence of this Document alone, does not automatically stall the part/component/assembly. work in accordance with the national regulations of an Airworthiness the Airworthiness Authority of the country specified in block 1, it is staller ensures that his/her Airworthiness Authority accepts parts/ from the Airworthiness Authority of the country specified in block 1.	
aircraft maintenance rec	and 19 do not constitute installation certification. In all cases ords must contain an installation certification issued in accordance ions by the user/installer before the aircraft may be flown.	-
		of a

Serial No.

Data	Ti	me		Cinnet	License
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	Number
3/28/10	47.	9	Changed oilly filter with 10,28-50, shanzed		
			Filter Inspected filter-noveral, test Riv	c b) m	
	-		checked forcheaks-none	Me Midself	5356/00
8/2/00	24.	9	Changes oil Velle y x 20-50, inspected	~ 10	
			Leghage no leaks found. Test RAN FOR	W. Bul	50356/101
				The same of the sa	200001
1/4/00	/08	2	Changed oil (15-50 Aero) + filter, Cuty	1.000	
	-	-	insported fifter-no contentionals pul-leak greated-OK	The Medical	503561109
	_	\vdash	Page Total Brought Forward All Repair Data Must Bear Certificated Mechanic, and	d his Rating and	a
- : : :			Total to Date Certificate Number MUST	be Shown.	

Serial No. ____

Date	Ti	me				License
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS		Signature	Number
1/27/01	131.	/	Changed Oil (15-50) Ineperfect fitter -OK	gera) + F. Har. Cat	MAD.N	60351.10b
			The FIRE TOX.	KAN FOR CHEGORA -UN	Mary and	# V.5 >6 /VV/
				2.5	L+1 - 1 - 1	
			Total Control			
						-
				A Section of the Contract of t		
			Page Total	All Repair Data Must Be	ar the Endorsement of a	
			Brought Forward	Certificated Mechanic, a Certificate Number MUS	nd his Rating and	
			Total to Date	Certificate Number MUS	i be snown.	

Serial No.

Date	Ti	me				Cianatura	Licens	
Date	Hrs Min REPAIRS - ADJUSTMENTS - SERVICE - REMARKS				Signature	Numbe		
							100	
				ARAPAHO				
	1.	2760 E	AST CONTROL TO		VOOD, COLORADO 80		550000000000000000000000000000000000000	
	N	140RN	M Lycoming	TIO-540-AFIB	S/N: L-10413-61A	Total Time: 13	4.7	
	5 March 2001 Tach: 134.7 100 Hour inspection for annual completed this date using the Mooney M20M inspection form as a guide							
	Com	pressio	on test #1) 78/80 #2)	76/80 #3) 79/80 #4)	76/80 #5) 78/80 #6) 78/8	0. Cut oil filter o	pen and	
	inspe	ected, r	no contaminated noted	d. No oil change at this	time. Cleaned and resea	led fuel injectors. (Cleaned,	
					gine timing. Checked as			
	Adju	sted an	nd saftied Density co	ntroller per Lycoming	SI 1187J. Adjusted eng	ine idle mixture. I	nstalled	
					mps and nuts. Installed a			
		-			93-02-05 (fuel injection)			
					er adapter plate) N/A			
					THIS ENGINE HAS			
					ON AND WAS DETER			
$\neg \neg$	200000000000000000000000000000000000000		THY-CONDITION.					

ENGINE LO	G
-----------	---

Serial No.

Date	Time Hrs Min	REPAIRS - ADJU	STMENTS - SERV	/ICE - REMARKS		Signature	License Numbe
	S/N ENG MODE ENG S/N THE AIRCRAFT AND/O AIRWORTHY FOR RET SIGNATU A&P	140RM M20M 27-0287 TIO540AF1E I L0141360A PRE JOHN THE DATE S RE JOHN TO SERVICE ON THE DATE S RE JOHN TO SERVICE ON THE DATE S	CHANDLI CHAI (480)	TR AVIATION INC ER MUNICIPAL NDLER, AZ 732-9118 ECTED IN ACCORDANCE WITH CURRENT FI DETAILS OF THE REPAIR ARE ON FILE AT AUTHORIZED NO. QTS A/S 15W50	WO# HOBBS TACH TOTAL TOTAL 31686		
	filter. Ground ran & leak checked satisfactory. END						
		Page Total Brought Forward Total to Date		All Repair Data Certificated Med Certificate Num	hanic, and	the Endorsement of a his Rating and be Shown.	

Serial No.

License Number

CROWNAIR
FAA Approved Repair Station #CWNR273K
3753 John J. Montgomery Dr.
San Diego, CA 92123

_	Reg #	N1	40RM	

Date: October 4, 2001

Model: M20M

Hobbs: 200.1

SN: 27-0281

Changed the oil and filter, serviced with 10 quarts Shell 15W50.

The aircraft identified above was repaired and inspected in accordance with current Federal

Aviation Regulations and was approved for return to service. Pertinent details of the repair are on

file at this repair station under Work Order # LT-01-01289/

Serial	No.	_

CROWNAIR		Lice
proved Repair Station #C	CWNR273K	Null
		_
San Diego, CA 72125	*	_
Model: M20M	SN: 27-0287	_
		_
	accordance with augment Fodoral	
repaired and inspected in a	Destinant details of the renair are on	_
		4
ork Order # L1-01-01367.		
/		_
1	to last	
	thorized Representative	
-	Model: M20M Hobbs: 225.3 ed with 10 quarts Shell 150 repaired and inspected in a	oproved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123 Model: M20M SN: 27-0287

CHICINIC I AA

CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

License Number

— Reg. #. N140RM

Model: M20M 2002 Hobbs: 236.8 S/N: 27-0287 SNEW: 236.8

Date: March 8, 2002

Changed oil and replaced filter serviced system with 10 qts Shell 15/50W. Took oil and sample and sent for analysis. CW AD 93-02-05 inspection of fuel nozzles and lines. Compressions as

follows: 1. 76/80 2. 74/80 3. 77/80 4. 74/80 5. 74/80 6. 74/80.

I certify that this engine has been inspected in accordance with an **Annual Inspection** and has been determined to be in airworthy condition. Pertinent details of the repair are on file at this

repair station under Work Order # LT-02-01443

CROWNAIR

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

L	.ic	Эe	n	S	e
١	łυ	III	nt	De	r

_ Reg # N140RM Model: M20M _ Date: July 09, 2002 Hobbs: 261.3

Changed the oil and filter, serviced with 10 quarts Shell 15W50.

The aircraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on

file at this repair station under Work Order # LT-02-0156.

Authorized Representative

SN: 27-0281

Page Total
Brought Forward
Total to Date

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

CROY	WNAIR
AA Approved Repai	r Station #CWNR273K
	Aontgomery Dr.
San Diego	, CA 92123

icense umber

Reg # N140RM Model: M20M SN: 27-0281 Date: August 26, 2002 Hobbs: 282.5

Changed the oil and filter, serviced with 10 quarts Shell 15W50.

The aircraft identified above was repaired and inspected in accordance with current Federal

Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order # LT-02-01614.

Authorized Representative

	Page Total	
	Brought Forward	
1	Total to Date	

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

Serial No.

CROWNAIR
FAA Approved Repair Station #CWNR273K
3753 John J. Montgomery Dr.
San Diego, CA 92123

	9790	
Reg # N140RM Date: November 14, 2002	Model: M20M Hobbs: 301.5	SN: 27-0281

Changed the oil and filter, serviced with 10 quarts Shell 15W50.

The aircraft identified above was repaired and inspected in acc	cordance with current Federal
Aviation Regulations and was approved for return to service.	Pertinent details of the repair are on
file at this repair station under Work Order # LT-02-01696	

Authorized Representative

.

License Number

CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

Model: M20M

Reg. II.	TATAOLCIAT	MIOGOL. MIZON	1 5/1	1. 2/ 020/
Date:	March 21, 2003	Hobbs: 312.8	SN	EW: 312.8
Change	ed oil and replaced filter	serviced system with 10	ats Shell 15/50W	Took oil ar

Dea # NILAODM

Changed oil and replaced filter serviced system with 10 qts Shell 15/50W. Took oil and sample and sent for analysis. **CW AD 93-02-05** inspection of fuel nozzles and lines. Compressions as follows: 1. 76/80 2. 76/80 3. 76/80 4. 78/80 5. 78/80 6. 76/80.

I certify that this engine has been inspected in accordance with an **Annual Inspection** and has been determined to be in airworthy condition. Pertinent details of the repair are on file at this repair station under Work Order # LT-03-01818.

Authorized Representative

S/NI: 27-0287

License Number

:	N	CI	N		1	0	C
•	•••			_	•		

Date

-Reg # N140RM

Date: June 5, 2003

CROWNAIR

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

Model: M20M

SN: 27-0287 Hobbs: 336.9

Cartal Ma

Changed the oil and filter, serviced with 10 quarts Shell 15W50. Took oil sample for analysis.

The aircraft identified above was repaired and inspected in accordance with current Federal

Aviation Regulations and was approved for return to service. Pertinent details of the repair

are on file at this repair station under Work Order #LT-03,01902.

Authorized Representative

ENGINE LOG

Serial No.

	the state of the s			200
	Time	CROWNAIR		License Number
-	EAA A	pproved Repair Station #0	TWND273V	-
_				
		3753 John J. Montgomery		
-		San Diego, CA 92123		
_				
	Reg # N140RM	Model: M20M	SN: 27-0281	
-	Date: September 30, 2003	Hobbs: 359.5		
_	•			-
	Changed the oil and filter, service	ed with 10 quarts Shell 15V	V50.	
-	onanges are on any more, services	4		
_	The aircraft identified above was	renaired and inspected in a	ccordance with current Federal	-
_			Pertinent details of the repair are o	
_			ertificing details of the repair are o	11
-	file at this repair station under W	ork Order # L1-03-02009	1/	-
_		U		
		Ť.	1 (, (
			my -	
		Au	thorized Representative	

FAA Approved Repair Station #CWNR273K

Da		San Diego, CA 92123		
	Reg. #. N140RM	Model: M20M	S/N: 27-0287	
	Date: February 17, 2004	Hobbs: 381.3	SNEW: 381.3	
_	Changed oil and replaced filter s and sent for analysis. CW AD 02 follows: 1. 76/80 2. 76/80 3. 74/8	2-26-01 inspection of fuel nozzl		
	I certify that this engine has been been determined to be in airworth repair station under Work Order	ny condition. Pertinent devails of	- / .	
		()		

Authorized Representative

Brought Forward Certificated Mechanic, and his Rating and Certificate Number MUST be Shown. Total to Date

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

License Number

Reg # N140RM Date: April 8, 2004 Model: M20M Hobbs: 405.4 SN: 27-0281

Changed the oil and filter, serviced with 10 quarts Shell 15W50.

The aircraft identified above was repaired and inspected in accordance with current Federal

Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order # LT-04-02263

Authorized Representative

Page Total	
Brought Forward	
Total to Date	

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

San Diego, CA 92123

Reg # N140RM

Model: M20M

SN: 27-0281

License

Date: December 10, 2004 Hobbs: 428.8

Changed the oil and filter, serviced with 10 quarts Shell 15W50. Cleaned and gapped all sspark plugs. Inspected and cleaned induction air filter..

The aircraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order # LT-04-02397

Authorized Representative

FAA Approved Repair Station #CWNR273K

3753 John J. Montgomery Dr.

San	Diego,	CA	92	123
-----	--------	----	----	-----

License Number

Reg. #. N140RM

Model: M20M

S/N: 27-0287

Date: April 3, 2005

Hobbs: 433.3

SNEW: 433.3

CW AD 02-26-04 inspection of fuel nozzles and lines. Compressions as follows: 1. 77/80 2.

74/80 3. 73/80 4. 75/80 5. 73/80 6. 75/80. Removed left magneto replaced points and reinstalled.

I certify that this engine has been inspected in accordance with an **Annual Inspection** and has been determined to be in airworthy condition. Pertinent details of the repair are on file at this repair station under Work Order # LT-05-02502.

Authorized Representative

Page Total	
Brought Forward	
Total to Date	

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

ΕN	G	IN	E	L	0	G
	_		_	_	•	•

Sprial No.

-	-				
	\mathbf{n}		T.T	A 1	IR
					117
		, ,,			

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

License
Number

Reg # N140RM

Model: M20M

SN: 27-0281

Date: July 20, 2005 Hobbs: 455.9

Changed the oil and filter, serviced with 10 quarts Shell 15W50. Took oil sample sent for analysis.

The aircraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on

file at this repair station under Work Order # LT-05-02625 /

Authorized Representative

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr.

San Diego, CA 92123

Reg # N140RM

Model: M20M

SN: 27-0281

License

Number

Date: October 12, 2005

Hobbs: 482.1

Changed the oil and filter, serviced with 10 quarts Shell 15W50.

The aircraft identified above was repaired and inspected in accordance with current Federal

Aviation Regulations and was approved for return to service. Pertinent details of the repair are on

file at this repair station under Work Order # LT-05-02625

Authorized Representative

Page Total All Repair Data Must Bear the Endorsement of a **Brought Forward** Certificated Mechanic, and his Rating and Certificate Number MUST be Shown. Total to Date

CROWNAIK

FAA Approved Repair Station #CWNR273K	
3753 John J. Montgomery Dr.	
San Diego, CA 92123	License Number
Reg. #. N140RM Model: M20M S/N: 27-0287 Date: April 18, 2006 Hobbs: 504.3 SNEW: 504.3	
and sent for analysis. CW AD 02-26-01 inspection of fuel nozzles and lines. Compressions as follows: 1. 76/80 2. 76/80 3. 78/80 4. 76/80 5. 76/80 6. 76/80. Replaced induction air filter to CW AD 84-26-02, due again in 500 hrs. Removed both magnetos Replaced block and rotor and	
I certify that this engine has been inspected in accordance with an Annual Inspection and has been determined to be in airworthy condition. Pertinent details of the repair are on file at this repair station under Work Order # LT-06-02924.	
	Reg. #. N140RM Model: M20M S/N: 27-0287 Date: April 18, 2006 Hobbs: 504.3 SNEW: 504.3 Changed oil and replaced filter serviced system with 10 qts Shell 15/50W. Took oil and sample and sent for analysis. CW AD 02-26-01 inspection of fuel nozzles and lines. Compressions as follows: 1. 76/80 2. 76/80 3. 78/80 4. 76/80 5. 76/80 6. 76/80. Replaced induction air filter to CW AD 84-26-02, due again in 500 hrs. Removed both magnetos Replaced block and rotor and rotor gear in both magnetos and the points in the right magneto. Reinstalled magnetos and timed to 25 degrees. I certify that this engine has been inspected in accordance with an Annual Inspection and has been determined to be in airworthy condition. Pertinent details of the repair are on file at this

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

:6	١n	S	е	r
3.7		37	7	
ΙП	nt	Œ	зſ	

Reg # N140RM
Date: July 14, 2006

Model: M20M Hobbs: 527.4 SN: 27-0281

Changed the oil and filter, serviced with 10 quarts Shell 15W50.

The aircraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order # LT-06-0302

Authorized Representative

 1 1	-
Brought Forward	
 Total to Date	

All Repair Data Must bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

ENGINE LOG

CROWNAIR

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr.

San Diego, CA 92123

Reg # N140RM

Model: M20M Hobbs: 549.8 Date: January 4, 20067

SN: 27-0281

License Number

Changed the oil and filter, serviced with 10 quarts Shell 15W50.

The aircraft identified above was repaired and inspected in accordance with current Federal

Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this repair station under Work Order # LT-06-03226

Authorized Representative

Total to Date

Certificate Number MUST be Shown.

		ENGINE LOG	Serial No.	
	FAA	Approved Repair Station #CWN 3753 John J. Montgomery Dr.		Licens Numbe
		San Diego, CA 92123		
Reg. #.	N140RM	Model: M20M	S/N: 27-0287	-
-	April 27, 2007	Hobbs: 560.4	SNEW: 560.4	_
	76/80 4. 74/80 5. 76/8	of fuel nozzles and lines. Compres	ssions as follows: 1. 76/80 2.	_
70,00 31		^		
I certify to	ermined to be in airwo	en inspected in accordance with an		
I certify to		en inspected in accordance with an orthy condition. Pertinent details of the rr # LT-07-03355.		
I certify to	ermined to be in airwo	en inspected in accordance with an of the condition. Pertinent details of the condition of the condition. Pertinent details of the condition. Pertinent details of the condition. Pertinent details of the condition.	the repair are on file at this	

1.00

ENGINE LOG

Serial No. ____

			Oction 140.	
1	Time			'icense
_		CROWNAIR		
	FA	A Approved Repair Station #CWNR273	K	
		3753 John J. Montgomery Dr.		
_		San Diego, CA 92123		_
_				
	Reg # N140RM		7-0281	
_	Date: June 28, 2007	Hobbs: 541-3 572.0		
_	Changed the oil and filter, s	erviced with 10 quarts Shell 15W50.		
_				
	The aircraft identified above	was repaired and inspected in accordance	with current Fede	eral
_	Aviation Regulations and wa	is approved for return to service. Pertinent	details of the rer	pair are on
_		er Work Order # LT-07-03480.	1	
_				
				112 11
		Authorized D.	annocontative.	_

PRIORIE

1

	CROWNAIR		
FAA	Approved Repair Station #C	CWNR273K	License
	3753 John J. Montgomery	Dr.	Number
	San Diego, CA 92123		
Reg # N140RM	Model: M20M Hobbs: 591.3	SN: 27-0281	
Date: august 30, 2007	110003. 571.5		
Changed the oil and filter, serv			
The aircraft identified above we Aviation Regulations and was a file at this repair station under	approved for return to service	. Feltiment details or the re	pair are on
	Au	thorized Representative	-
		. 11	-
Total to Date	Certi	ficate Number MUST be Shown.	

ENGINE LOG

Serial No.

SN: 27-0287

nse

Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

Reg. #: N140RM 03/17/08 Date:

Model: Mooney M20M

Hobbs Time: 613.5

Changed oil and filter, serviced with 10 quarts Shell 15W50 oil.

The aircraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this Repair Station under work order

LT-08-03764.

Authorized Representative

CWNR273K

TRICINIT I OC

Carial Na

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

Reg. #: N140RM

Date:

08/28/08

Model: Mooney M20M

Hobbs Time: 638.4

SN:

27-0287

Changed oil and filter, serviced with 10 quarts Shell 15W50 oil.

I certify that with respect to the work performed this aircraft or component was repaired and inspected in accordance with current FAA regulations. Only those items specified in the Work Order have been inspected and found to be Airworthy and Returned to Service. Pertinent details of this repair are on file at this Repair Station under Work Order #LT-08-03936.

Authorized Representative

Total to Date

Certificate Number MUST be Shown.

LYCOMING TIO-540-AF1B S/N L-10413-61A IRAN INSPECTION / CRANKSHAFT CHANGE IAW MANUAL # 60294-7-9 AND LYCOMING SB 569A, WITH THE FOLLOWING PARTS INSTALLED: 1EA 13E47622 CRANKSHAFT S/N V537946573 (FROM CRANKSHAFT KIT P/N 05K23579), 1EA LW-19340 CAMSHAFT, 2EA 71903-A BUSHING, 2EA 71903-A BUSHING, 4EA 71903-B BUSHING, 6EA 73772 NOZZLE ASM, 12EA 72877R REGROUNG LIFTER, 1EA 1028-B BALL, 1EA LW-11713 OIL PSI SPRING, 1EA STD-2231 RET RING, 2EA 76788 ROLLER, 2EA LW-15558 ROLLER, 1EA STD-1211 PLUG, 1EA AN565B1032H5, 1EA STD-2168 NUT, 3EA LW-31H0.88 BOLT, 1EA STD-1737 RET RING, 2EA LW-25-0.63 BOLT, 1EA 05K23463 IMPELLER KIT, 1EA AS3582-009 O-RING, 1EA MS16562-28 PIN, 1EA STD-95 KEY, 1EA CH48110-1 OIL FILTER, 1EA LW-11485 SHROUD TUBE, 6EA STD-1821 HOSE, 12EA LW-15592-5-05 CLAMP, 12EA RHB37E SPARK PLUG, 4EA STD-1901 STUD, 6EA 69603 HOSE, 12EA LW-15592-8-28 CLAMP, 12EA LW-15592-8-24 CLAMP, 15EA MS21044N3 NUT, 4EA STD-2044 NUT, 6EA LW-18737 HOSE, 16EA LW-15592-5-04 CLAMP, 2EA STD-2048 HOSE, 8EA 71907 PLATE, 8EA LW-14820 RET RING, 1EA MS29512-08 O-RING, 1EA AEL19600 VERNATHERM, 1EA LW-RF2.239-.070 O-RING, 12EA 951391 PACKING, 1EA STD-1211 PLUG, 6EA 77611 GASKET, 12EA AEL60009 KEY, 12EA MS13997-3 KEY, 6EA MS13998-3 CAP, 6EA AEL13790 SHAFT, 12EA AEL12892 THRUST BUTTON, 2EA 67542 BEARING, 4EA 68H22624 CUSHION, 1EA STD-1339 PLUG, 1EA MS29512-10 O-RING, 6EA STD-2180 HOSE. THE FOLLOWING PARTS O.K. FOR CONTINUE TIME IN SERVICE: 1EA 11E24003-S3 CRANKCASE I.D. # K0955, 6EA 16A22023 CYLINDER ASM, 1EA 6361 MAGNETO S/N 99110238, 1EA 6360 MAGNETO S/N 99071759, 1EA M2965 HARNESS, 1EA RG17980U/M FUEL PUMP S/N C4900, 1EA 149-24LS STARTER S/N F4L-369905, PORT MATCH & FLOW BALANCE CYLINDERS, TEST RUN 1.5 HOURS. ALL INFORMATION ON FILE A'T LY-CON REBUILDING CO. REFERENCE WO 33153.

PAGE 1 OF 2 LY-CON REBUILDING CO. 8231 Doe Avenue Visalia, CA 93291 (559) 651-1070

Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

Reg. #: N140RM	Model: Mooney M20M	SN:	27-0287	
Date: 06/30/09	Hobbs Time: 657.1		\ -	
Installed new push rod seals on cyli	inders #1, #3 and #5. Installed new gasket.			
/	paired and inspected in accordance with current Pertinent details of the repair are on file at this			
LT-09-04229.				
Authorized Representative	CWNR273K			
1 1				

Service Bulletins, Letters, Instructions & A D Notes DATE Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123 Reg. #: N140RM Model: Mooney M20M SN: 27-0287 Date: 07/20/09 Hobbs Time: 669.2 Changed oil and filter, serviced with 10 quarts Shell 15W50 oil. The airgraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this Repair Station under work order LT-09-04290. Authorized Representative CWNR273K

	Service Bulletins, Letter
DATE ————	Instructions & A D Note

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

Reg. #: N140RM Date: 09/30/09

Model: MOONEY M20M Hobbs Time: 392.1 694.0

SN: 27-0287

Changed oil and filter, serviced with 9 quarts Shell 15W50 oil. Performed compression check on all cylinders #1- 78, #2- 76, #3-75, #4- 76, #5-77, #6-76.

The aircraft identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was approved for return to service. Pertinent details of the repair are on file at this Repair Station under work order LT-09-04417.

Anthorized Representative

CWNR273K

Service Bulletins, Letters, Instructions & A D Notes DATE

Air 88 Inc. dba CROWNAIR

FAA Approved Repair Station #CWNR273K

3753 John J. Montgomery Dr.

San Diego, CA 92123

4/07/2010 HOBBS: 705.8 S/N: L-10413-61A S/N: 27-0287 705.8

705.8

TSN:

TTAF:

Maintenance performed:

LYCOMING

N140RM

Completed Annual Inspection I/A/W Crownair 100 Hour/Annual Inspection Checklist, Form CA 105.

TIO-540-AFIB

MOONEY M20M

Changed oil and filter, serviced with 10 quarts Shell 15-50 oil

- Cut open and inspected oil filter
- Complied with AD 2008-14-07 fuel injector lines and clamps, by inspection

- Replaced crankshaft seal with new P/N: LW-13792
- Tightened exhaust "V" clamps
- Compressions are as follows- #1-78, #2-78, #3-77, #4-77, #5-78, #6-76

I certify that this engine and propeller have been inspected in accordance with an Annual Inspection and were determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details

of the repair are on file at this agency under Work Order #LT-10-04651.

Authorized Representative

YE DA	Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWiNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123	-
_	N140RM MOONEY M20M S/N: 27-0287	-
_	7-7-2010 HOBBS: 721.4	-
_	- Changed oil and filter P/N: Ch48110-1, serviced with 10 quarts of 15W50 oil	-
_	- Resealed #4 cylinder pushrod tubes with seal(s) P/N: 70310 and LW18661	-
	- Re torqued oil drain line clamps and intake pipe bolts on left cylinder bank	
	- Washed oil soaked cowling and engine	
_		-
_	I certify that this ENGINE has been inspected in accordance with current FARs and was determined to be in airworthy condition.	-
_	all worthly condition.	-
_	I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of	
	the repair are on file at this agency under Work Order #LT-10- 04820	
_	a Robela	-
_	Authorized Representative	-

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests Entries must be endorsed with Name, Ra Facility. (See back pages for other specific	iting and Certificate Number of Technician or Repair
			FAA	Air 88 Inc. dba CROWNAIR Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123	
	nance perform		viced with 9	Mooney M20M Hobbs: 742.6 HRS Qts of Aeroshell 15W-50 oil.	S/N: 27-0287
I certif	FAA regula hy and return	respect to	the work		and inspected in accordance with we been inspected and found to be at this agency under Work Order No.

		-
YI	Air 88 Inc. dba CROWNAIR	1
	FAA Approved Repair Station #CWNR273K	1
	3753 John J. Montgomery Dr.	1
-	San Diego, CA 92123	F
	San Diego, CA 72125	1
	LYCOMING IO-540-AFIB S/N: L-10413-61A	
		-
-	4-29-2011 HOBBS: 757.2 TSN: 757.2	-
		L
	Maintenance performed:	
	 Completed Annual Inspection I/A/W Crownair 100 Hour/Annual Inspection Checklist, Form CA 105. 	_
	 Changed oil and filter P/N: CH48110-1, serviced with 10 quarts of 15W50 oil. 	
	- Cut open oil filter, inspected for contamination, found paint particles, took oil sample and sent out for	_
	analysis	
	- Installed one new spark plug P/N: RHB37E	
		_
	- Complied with AD 2008-14-07, fuel injector lines inspection	
	- Checked magnetos points and gears for wear. Replaced left and right contact points with new P/N: M3081,	
	installed new coil on left magneto P/N: K3975, reassembled both magnetos and time to engine, installed new	
	gaskets.	_
	 Replaced air filter with new P/N: ED04028 	
	- Cleaned, scrapped and replaced all rocker cover gaskets with all new silicone gaskets	_
	- Compressions are as follows- #1-77, #2-77, #3-75, #4-76,#5-77,#6-74	
		_

	at this engine has y condition.	been inspected in accordance with an Annual Inspection and was determined to be	pair
accordance	with current Fee	requested by the owner/operator and listed above was repaired and inspected in eral Aviation Regulations and was found to be airworthy for return to service. Details agency under Work Order #LT-11-05261. Authorized Representative	
	T		
	1 4	(C) An	

EAR:	TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Re Entries must be endorsed with Name, Rating a	프랑 맛있지만 맛있다면 가지 않지 않는데 하지만 하지 않는데 하지만 하지만 하지만 하지만 하는데
				Air 88 Inc. dba CROWNAIR	
			FA	A Approved Repair Station #CWNR273K	
				3753 John J. Montgomery Dr.	
				San Diego, CA 92123	
N14	ORM			Mooney M20M	S/N: 27-0287
9-09				Hobbs: 784.4 Hrs	
-	Changed oil engine.		Serviced wit	th 9 Qts of Aeroshell 15W-50 oil and installe	ed new CH48110-1 oil filter. Washed
curr	ent FAA re	gulations.	Only thos	ork performed this engine was repaired the items specified in the work order have trinent details of this repair are on file at	ve been inspected and found to be

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs a Entries must be endorsed with Name, Rating and Cer Facility. (See back pages for other specific entries.)	
- [Al- ee I - II - Chours I In	
				Air 88 Inc. dba CROWNAIR	
				FAA Approved Repair Station #CWNR273K	
-0.				3753 John J. Montgomery Dr.	
				San Diego, CA 92123	
•	N140RM			Mooney M20M	SAL 27 0297
	10-21-11			Hobbs: 802.7 Hrs	S/N: 27-0287
	Maintenance	nerforme	d·	110003. 602.7 1113	
.				with 9 Qts of Aeroshell 15W-50 oil and installed ne	w CH48110-1 oil filter
.	- Innige	on and m	en servicea	The second residence in the second in the installed lie	w chiasi to-1 on finer.
	I certify tha	t with res	spect to the	work performed this engine was repaired as	nd inspected in accordance with
_	current FAA	regulation	ons. Only	those items specified in the work order have	been inspected and found to be
	airworthy an	d returne	d to service	Pertinent details of this repair are on file at the	is agency under Work Order No.
-	PA-11-05530.			Torument details of this repair are on the at the	is agency under work order ivo.
				OCH	F) / H W/
-				Adherize	d Representative
				Addienze	a representative

Page 1 of 2

Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

N140RM 5-01-12

Lycoming Engine

TIO-540-AFIB

Mooney M20M

Hobbs: 814.1 Hrs

S/N: L-10413-61A

S/N: 27-0287

TSN: 814.1 Hrs

Maintenance performed:

- Completed Annual Inspection I/A/W Crownair 100 Hour/Annual Inspection Checklist, Form CA 105.
- Changed oil and filter. Serviced with 9 Qts of Aeroshell 15W-50 oil and installed new CH48110-1 oil filter.
- Cut open old oil filter and inspected with no metal contamination found.
- Compressions are as follows: #1. 78/80 #2. 70/80 #3. 74/80 #4. 70/80 #5. 75/80 #6. 72/80.
- Complied with AD 2011-26-04 by inspection of fuel injector fuel lines and clamps I/A/W Lycoming MSB 342F) and no defects noted at this time. Due every 100 Hrs or annual inspection whichever occurs first. Due again @ 914.1 Hrs or May 2013.
- Verified AD 2011-13-03 and found N/A due to time on turbocharger.
- Verified AD 2012-03-06 and found N/A due to Precision fuel servo installed.
- Verified AD 2012-03-07 and found N/A due to engine being fuel injected and has no carburetor.
- Retimed right magneto to match left at 20°.

Page 2 of 2

Air 88 Inc. dba CROWNAIR

FAA Approved Repair Station #CWNR273K

3753 John J. Montgomery Dr.

San Diego, CA 92123

Lycoming Engine

N140RM Mooney M20M S/N: 27-0287 5-01-12 Hobbs: 814.1 Hrs TSN: 814.1 Hrs

TIO-540-AFIB

I certify that this **engine** has been inspected in accordance with an **Annual Inspection** and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order #LT-11-05261.

Authorized Representative

S/N: L-10413-61A

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endors	ections, Tests, Repairs and ed with Name, Rating and Certific es for other specific entries.)	d Alterations ate Number of Technician or Repair
ATE				гасшу. (See раск раде	is for other specific entries.)	
		BUTLE	RAIRCRAI	FT 705 SE SALMON A	VE. REDMOND, OR 97756	(541) 923-1355
NI	40RM	DOTEL		odel: M20M	S/N: 27-0287	August 14, 2012
_ Hobbs: 838.1		W/O: N140RM8-8-12				
Re	moved and re	placed the	starter (Sky-T	Tec M/N 149-24LS, S/N	F4L-369905) with a new unit (S/N F4L-231202). Installed a
					ormed an operational check of t	[[[[[[[[[[[[[[[[[[[
		_				
	Cal S	1	Rich	ard Ingram A&P 542083	175	
_				and ingram / ice 5 12005		
	-					
		BUTLER	AIRCRAFT	T 705 SE SALMON AV	E. REDMOND, OR 97756 (5	41) 923-1355
N14	0RM			O-540-AF1B	S/N:	August 14, 2012
Hob	bs: 838.1			N140RM8-8-12	57.11	August 14, 2012
		9 ats. Aero	7 (20)		nnion CH48110-1 Performed	engine run and leak check, no
defe	cts noted Cu	t open oil f	ilter to check	for contaminates, none f	ound	engine run and reak check, no
	-	0	mer to eneek	ioi contaminates, none i	odila.	
_	-0	0	Richar	rd Ingram A&P 54208317	75	-
_				14 THE COURT PARK TO THE PROPERTY OF THE PARK TO THE P		
				ag.a / 10051		

EAR:	TACH FLIGHT TIM	Description of Inspections, Tests, Repairs Entries must be endorsed with Name, Rating and C	
		Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123	
		San Diego, Cri 72125	
Ly	ycoming Engine	TIO-540-AF1B	S/N: L-10413-61A
NI	140RM	Mooney M20M	S/N: 27-0287
2-2	27-13	Hobbs/ACTT: 860.5 Hrs	TSN: 860.5 Hrs
M	aintenance performed:		
-	Changed oil and filter. Ser Took oil sample and sent o	viced with 9 Qts of Aeroshell 15W-50 oil and installed new ut for analysis.	w CH48110-1 oil filter.
cu air	irrent FAA regulations. (on the work performed this engine was repaired and only those items specified in the work order have revice. Pertinent details of this repair are on file at the	been inspected and found to b

Page 1 of 2	Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR2 3753 John J. Montgomery Dr.	73K
	San Diego, CA 92123	
Lycoming Engine	TIO-540-AFIB	S/N: L-10413-61A
N140RM	Mooney M20M	S/N: 27-0287
6-03-13	Hobbs: 867.2 Hrs	TSN: 867.2 Hrs
	Serviced with 9 Qts of Aeroshell 15W-50 oil and and inspected with no metal contamination found.	
 Took oil sample and se 	em our for analysis.	
 Took oil sample and se Compressions are as fe 	ollows: #1. 76/80 #2. 76/80 #3. 76/80 #4. 76/	80 #5. 76/80 #6. 76/80.

Page 2 of 2

Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

 Lycoming Engine
 TIO-540-AFIB
 S/N: L-10413-61A

 N140RM
 Mooney M20M
 S/N: 27-0287

 6-03-13
 Hobbs: 867.2 Hrs
 TSN: 867.2 Hrs

Removed leaking vernatherm valve, cleaned sealing surfaces, reinstalled, tightened and safety wired. Ran
engine and no leaks found.

I certify that this engine has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-13-06161.

Authorized Representative

EAR:	RECORDING	TODAY'S	TOTAL	Description of Inspections, Tests, Repa	airs and Alterations
				Air 88 Inc. dba CROWNAIR	
			F	AA Approved Repair Station #CWNR273K	
1				3753 John J. Montgomery Dr.	
				San Diego, CA 92123	
Lyc	coming Engine			TIO-540-AF1B	S/N: L-10413-61A
N14	40RM			Mooney M20M	S/N: 27-0287
9-1	6-13			Hobbs/ACTT: 887.0 Hrs	TSN: 887.0 Hrs
-	Changed oil engine. Took oil sam	and filter.		vith 9 Qts of Aeroshell 15W-50 oil and installed alysis.	d new CH48110-1 oil filter. Washed
cur	rent FAA reg	gulations.	Only the	ork performed this engine was repaired a see items specified in the work order have Pertinent details of this repair are on file at the Authorized	been inspected and found to be

Page 1 of 2	Air 88 Inc. dba CROWNAIR		
	FAA Approved Repair Station #CWNR2	273K	
	3753 John J. Montgomery Dr.		
	San Diego, CA 92123		
Lycoming Engine	TIO-540-AFIB	S/N:	L-10413-61A
N140RM	Mooney M20M	S/N:	27-0287
6-09-14	Hobbs: 906.1 Hrs	TSN:	906.1 Hrs
Maintenance performed:			
- Completed Annual Insp	pection using Crownair Aviation Annual/100	Hour Inspection C	hecklist, Form (
105.			
 Changed oil and filter. S 	erviced with 10 Qts of Aeroshell 15W-50 oil as	nd installed new CI	H48110-1 oil filt
 Cut open old oil filter and 	d inspected with no metal contamination found.	•	
 Took oil sample and sent 	in for analysis.		
 Compressions are as follows: 	ows: #1. 76/80 #2. 76/80 #3. 72/80 #4. 76/	80 #5. 74/80 #6.	76/80.
 Complied with AD 2011 	-26-04 by inspection of fuel injector fuel lines	s and clamps I/A/V	V Lycoming M
	ed at this time. Due again @ 1006.1 Hrs or Jur	2015	

Page 2 of 2	Air 88 Inc. dba CROWNAIR	
	FAA Approved Repair Station #CWNR2	273K
	3753 John J. Montgomery Dr.	
	San Diego, CA 92123	
Lycoming Engine	TIO-540-AFIB	S/N: L-10413-61A
N140RM	Mooney M20M	S/N: 27-0287
6-09-14	Hobbs: 906.1 Hrs	TSN: 906.1 Hrs
gaskets P/N 77611 and 1	ust manifold, sent to Custom Aircraft Parts for gasket P/N 78084. plugs with new P/N RHB37E and installed on leading to the plugs w	•
I certify that this engine has in airworthy condition.	been inspected in accordance with an Annual	Inspection and was determined to
accordance with current Fede	requested by the owner/operator and listed a eral Aviation Regulations and was found to be a s agency under Work Order No. PA-14-06584	irworthy for return to service, Deta
	Auth	norized Representative

R:	RECORDING TACH	TODAY'S FLIGHT	TOTAL TIME IN	Description of Inspections, Tests, Rep Entries must be endorsed with Name, Rating an	
Г					
l				Air 88 Inc. dba CROWNAIR	
				FAA Approved Repair Station #CWNR273	K
				3753 John J. Montgomery Dr.	
				San Diego, CA 92123	
				TIO 540 4 DUD	
	ycoming Engi	ne		TIO-540-AF1B	S/N: L-10413-61A
	140RM			Mooney M20M	S/N: 27-0287
	0-13-14			Hobbs: 930.4 Hrs	
M	laintenance p				
:			 Serviced value sent out for a 	with 9 Qts of Aeroshell 15W-50 oil and installed analysis.	d new CH48110-1 oil filter.
cu ai	arrent FAA	regulation	s. Only th	work performed this engine was repaired nose items specified in the work order has Pertinent details of this repair are on file and Author	ave been inspected and found to b

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Entries must be endorsed with Name, Rat Facility. (See back pages for other specific	ting and Certificate Num	
Pag	ge 1 of 2		F	Air 88 Inc. dba CROWNAIR AA Approved Repair Station #CWNR2 3753 John J. Montgomery Dr. San Diego, CA 92123		
NI	coming Engine 40RM 1-15			TIO-540-AFIB Mooney M20M Hobbs: 940.5 Hrs	S/N:	L-10413-61A 27-0287 940.5 Hrs
<u>Ma</u>	Changed oil Cut open old Took oil sam Compression Complied wi annual inspec	and filter. oil filter a ple and se s are as fo th AD 84- ction. Due	Serviced with nd inspected nt in for analy llows: #1. 76 26-02 by inspectagain @ 104 1-26-04 by in	g Crownair Aviation Annual/100 Hour Instant 8 Qts of Aeroshell 15W-50 oil and instant with no metal contamination found. ysis. 6/80 #2. 76/80 #3. 70/80 #4. 74/80 #5 pection only of paper induction air filter at 10.5 Hrs or June 2016. Next replacement of 10.5 hrs of fuel injector fuel lines and claim @ 1040.5 Hrs or June 2016.	spection Checklist, For illed new CH48110-1 of 5. 76/80 #6. 76/80. and no defects found. due @ 1257.2 Hrs.	m CA 105. oil filter. Due every 100 Hrs or

R: RECORDING TODAY'S T	OTAL Description of Inspections, Tests,	Repairs and Alterations
Page 2 of 2	Air 88 Inc. dba CROWNAIR	
	FAA Approved Repair Station #CWNR2	73K
	3753 John J. Montgomery Dr.	
	San Diego, CA 92123	
Lycoming Engine	TIO-540-AFIB	S/N: L-10413-61A
N140RM	Mooney M20M	S/N: 27-0287
6-11-15	Hobbs: 940.5 Hrs	TSN: 940.5 Hrs
 AD 2015-02-07 To preve overhaul. 	ent the prop governor shaft set screw from comin	g loose is N/A at this time. Due at nex
	een inspected in accordance with an Annual Inspec	tion and was determined to be in airworthy
condition.		
I certify that only the work rec	juested by the owner/operator and listed above was	renaired and inspected in accordance with
	ations and was found to be airworthy for return to	
this agency under Work Order		7 . 0 8:20
		n-evil
	Adi	thorized Representative
		COMPANIES OF COMPANIES

YEAR:	RECORDING
24.03555	TACH

TODAY'S FLIGHT TOTAL TIME IN Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name Rating and Certificate Number of Technician or Repair

Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

Lycoming Engine

TIO-540-AF1B

S/N: L-10413-61A

N140RM

Mooney M20M

S/N: 27-0287

11-04-15

Hobbs: 962.9 Hrs

Maintenance performed:

- Changed oil and filter. Serviced with 10 Qts of Aeroshell 15W-50 oil and installed new CH48110-1 oil filter.
- Took oil sample and sent out for analysis.

I certify that with respect to the work performed this **engine** was repaired and inspected in accordance with current FAA regulations. Only those items specified in the work order have been inspected and found to be airworthy and returned to service. Pertinent details of this repair are on file at this agency under Work Order No. PA-15-07412.

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	를 하면 회에서 되어 있다. 그리고 아이트 아이트 아들이 눈이를 보고 있다면 하면 하지만 하는데 하는데 되는데 하는데 이렇게 하면 하는데	ng and Certificate Number of Technician or Repa
ATE				Facility. (See back pages for other specific	entries.)
Pa	ge 1 of 2			Air 88 Inc. dba CROWNAIR	
			1	AA Approved Repair Station #CWNR2	73K
1				3753 John J. Montgomery Dr.	
				San Diego, CA 92123	
Ly	coming Engin	e		TIO-540-AFIB	S/N: L-10413-61A
NI	40RM			Mooney M20M	S/N: 27-0287
6-0	06-16			Hobbs: 974.9 Hrs	TSN: 974.9 Hrs
Ma	aintenance pe	rformed:			
-	Completed 7	Annual In:	spection usin	g Crownair Aviation Annual/100 Hour Ins	spection Checklist, Form CA 105.
-				th 10 Qts of Aeroshell 15W-50 oil and inst	alled new CH48110-1 oil filter.
-				with no metal contamination found.	
-			ent in for anal		
-				6/80 #2. 78/80 #3. 76/80 #4. 76/80 #5	
-					and no defects found. Due again @ 1074.9
				t due @ 1257.2 Hrs.	
-				visual inspection of fuel injector fuel lines ue again @ 1074.9 Hrs or June 2017.	s and clamps I/A/W Lycoming MSB 342G

PATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs Entries must be endorsed with Name, Rating and C Facility. (See back pages for other specific entries.)		
Page	e 2 of 2		FA	Air 88 Inc. dba CROWNAIR AA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123		
Lvcc	oming Engine			TIO-540-AFIB	S/N:	L-10413-61A
	0RM			Mooney M20M	127.35	27-0287
6-06	- TV-1 005			Hobbs: 974.9 Hrs	TSN:	974.9 Hrs
		worn botto	m spark plug	s with new RHB-37E.		
	tify that this elition.	engine has	been inspect	ed in accordance with an Annual Inspection and	was determin	ned to be in airworthy

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-16-07651.

AR:	RECORDING	TODAY'S	TOTAL	Description of Inspections, Tests, Repairs an	d Alterations
				Comments Andretts	
				Crownair Aviation	
1				FAA Approved Repair Station #CWNR273K	
				3753 John J. Montgomery Dr.	
				San Diego, CA 92123	
L	ycoming Eng	ine		TIO-540-AF1B	S/N: L-10413-61A
	V140RM			Mooney M20M	S/N: 27-0287
1	1-09-16			Hobbs: 998.2 Hrs	
4.5	Maintenance	performed			
1-	Changed	oil and filte	r. Serviced	with 10 Qts of Aeroshell 15W-50 oil and installed new	CH48110-1 oil filter and safetie
			and leak ch	[18] [18] 전문 18] [18] [18] [18] [18] [18] [18] [18]	
-	Placed 2 (ats of Aero	snell 15 w-:	50 oil in aft baggage compartment per customer's reques	St.
r	egulations. O	nly those it	ems specifi	rk performed this engine was repaired and inspected ed in the work order have been inspected and found to agency under Work Order No. PA-16-07832.	
				() A.	therized Representative
				V Au	morized Representative

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Entries must be endorsed with Name, Rating and Certifical Facility. (See back pages for other specific entries.)		Repair
DATE	-	-		, domy, (eco cast, pages tal outer opening strates)		
_	N140RM	' '				
_	Mooney M		S/N27-0287		LEADIAG	
	Date: 8/2/17				LEUDINO	
_	Hobbs: 1025	.9			F	
—	Serviced engine	with 10 qts	Aeroshell 15W	50 (owner supplied).	AVIATION, INC.	_
_	Removed and in	spected oil t	ilier, no debris	found. Installed new CH48110-1 filter, torqued and safetyed.		
_	This aircraft is an	11/1/1		te for the work performed.		_
_	* Jall	n X fo	secret			
	Leading Ed	ge Avia	tion		80	
	FAA CRS#L	-				
	63342 Powell			R 97701 541-383-8825		
			, , , , , , , , , , , , , , , , , , , ,	341-303-0023		
		1		4		

EAR:		Description of Inspections, Tests, I Entries must be endorsed with Name. Ratin	Repairs and Alterations no and Certificate Number of Technician or Rena
Pag	e 1 of 2	CROWNAIR	
		FAA Approved Repair Station #CWNR2' 3753 John J. Montgomery Dr.	73K
		San Diego, CA 92123	
Lvc	oming Engine	TIO-540-AFIB	S/N: L-10413-61A
	IORM	Mooney M20M	S/N: 27-0287
	17-17	Hobbs: 1033.7 Hrs	TSN: 1033.7 Hrs
177.77	intenance performed:	1100001 100011 1110	10111 100011 1110
-	Researched ADs through	ection using Crownair Aviation Annual/100 Ho bi-weekly issue of this date, all ADs are in compliance	ce at this time.
:	Complied with AD 84-26-	ws: #1. 76/80 #2. 78/80 #3. 76/80 #4. 76/80 #5. •02 by inspection only of paper induction air filter at the case of the case	and no defects found. Due every 100 Hrs or
-	Complied with AD 2015-	19-07 by inspection of fuel injector fuel lines and cla Due again @ 1133.7 Hrs or October 2018.	

AR:	RECORDING TACH	TODAY'S	TOTAL TIME IN	Description of Inspections, Tests, Rep		
Pa	ge 2 of 2			CROWNAIR		
				FAA Approved Repair Station #CWNR273	K	
				3753 John J. Montgomery Dr.		
				San Diego, CA 92123		
	coming Engi	ne		TIO-540-AFIB	S/N:	L-10413-61A
100	40RM			Mooney M20M	S/N:	27-0287
10	17-17			Hobbs: 1033.7 Hrs	TSN:	1033.7 Hrs
COI	ndition.	s engine na	as been inspe	ected in accordance with an Annual Inspectio	n and was determine	ned to be in airworth
1.0	artify that on	ly the worl	raquastad l	by the cumer/energies and listed above and a		. 1
1.0	rant Fadaral	Aviation D	R requested t	by the owner/operator and listed above was re	epaired and inspect	ed in accordance wit
thi	s agency und	or Work Or	der No DA	and was found to be airworthy for return to se	rvice. Details of th	repair are on file a
	s agency und	CI WOIK OI	dei No. I'A-	T/-08124.	100	/
				- (Yakina	Core	
1				Autho	rized Representativ	e
				~		

Crownair Aviation FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

Lycoming Engine TIO-540-AF1B S/N: L-10413-61A N140RM Mooney M20M S/N: 27-0287 Hobbs: 1047.0 Hrs

Maintenance performed:

- Changed oil and filter. Serviced with 10 Qts of Aeroshell 15W-50 oil and installed new CH48110-1 oil filter and safety wired as required. Test ran and leak checked OK.
- Cut open old oil filter and checked for contamination, nothing abnormal found at this time.
- Oil sample taken and sent for analysis.

l certify that with respect to the work performed this **engine** was repaired and inspected in accordance with current FAA regulations. Only those items specified in the work order have been inspected and found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-18-08292.

RECORDING TODAY'S	Description of Inspections, Tests, Re	epairs and Alterations
Page 1 of 2	CROWNAIR	
	FAA Approved Repair Station #CWNR27	3K
	3753 John J. Montgomery Dr.	
	San Diego, CA 92123	
ycoming Engine	TIO-540-AFIB	S/N: L-10413-61A
N140RM	Mooney M20M	S/N: 27-0287
11-05-18	Hobbs: 1070.0 Hrs	TSN: 1070.0 Hrs
Maintenance performed:		
Completed Annual Insp	ection using Crownair Aviation Annual/100 Hour Insp	ection Checklist, Form CA 105.
	Serviced with 10 Qts of Aeroshell 15W-50 oil and insta	
Cut open old oil filter an	d inspected with no metal contamination found.	
Took oil sample and sen	t in for analysis.	
Compressions are as foll	ows: #1, 76/80 #2, 78/80 #3, 76/80 #4, 76/80 #5.	76/80 #6. 76/80.
	6-02 by inspection only of paper induction air filter ar	nd no defects found. Due again @ 1170.0
	replacement due @ 1257.2 Hrs.	
	5-19-07 by visual inspection of fuel injector fuel lines	and clamps I/A/W Lycoming MSB 342G
and no defects noted at t	his time. Due again @ 1170.0 Hrs or NOV 2019.	

YEAR:	TACH FLIGH		Description of Inspections, Tests Entries must be endorsed with Name, Ra	, Repairs and Alterations ting and Certificate Number of Technician or Rep
Page	2 of 2		CROWNAIR	
1 55		FA	A Approved Repair Station #CWNR2	73K
			3753 John J. Montgomery Dr.	
			San Diego, CA 92123	
Lyco	ming Engine		TIO-540-AFIB	S/N: L-10413-61A
N140			Mooney M20M	S/N: 27-0287
11-05	5-18		Hobbs: 1070.0 Hrs	TSN: 1070.0 Hrs.
I cert condi	*	nas been inspecte	d in accordance with an Annual Inspect	ion and was determined to be in airworthy
				repaired and inspected in accordance with
	nt Federal Aviation I gency under Work O			service. Details of the repair are on file at
uns a	gency under work O	ruer No. 174-18-0	70400.	ENDE DE 18
			-1	Authorized Representative
				/ rumonzed representative

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)						
	•			Engine Log						
	N140RM LEADING									
	Mooney N	M20M s	n: 27-028	7 7 11 1007 1						
-	Date: 06/28			WO# CSV-19-9125						
	checked god Changed oil visually insper REGARDING Signed	and filter cted – no n	Serviced winetal found. Le	### AL-231202 starter, installed new 149-24LS sn.HT032229. Operational #### Starter, installed new 149-24LS sn.HT032229. Operational ######### Starter, installed new 149-24LS sn.HT032229. Operational ###################################						
	-	-								

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	S/N 10AR : Mooney M2 FAA-P-874	M20M 16/2019 ven vac pump 30 and replai 20M MM P/N 40-52 safety v	MAN152 Dated Warning given to VE MENTIONED W	WO# CSV-19-0178 # VI # 1 [0

EAR:	RECORDING TACH	TODAY'S	TOTAL TIME IN					airs and Alterationd Certificate Number	
AT (GOLD WING A An AIRTRONICS IN		REG: N	140RM	WO#:	461	
_ `	Aviation		12380 Airport Ro- Jackson, CA 95642		MAKE:	LYCOMING	MODEL:	TIO-540-AF1B	
10	OCATION: INSPEC	CTION				L-10413-61A			
- SE	RVICE DESCRIPT	ION:			AFTT:	1116.50	TACH:	1116.50	
- EN	GINE: TT: 1116 50								
The Co	or work performed above	was done IAV	V Lyceening TiO-540 MMi endment 39-18269 Dated	75/80 4) 77/80 5) 76/80 (Maintenance Monual) and I Nov. 3, 2015 IAW paragraph aragraph (a) Replaced inc	d Mooney M2054 Mi	M. Ran engine up. o SB: 342G, für dieter	rts leend at this o	nose found. ine. Next Due Hubbs: 1613.5	
				n, IAW FAR 43 App. D an history 2021 or AFTT 12:6		neu to be arrivorthy i	al this time. Port	oumed operational run of engine ar	nd
	JANIE ZIE	MER/	PTE DATE: Date	ember, 09 2019					
_0	ERT: A&P. 3854	//	KIS DATE. Dec	emper, da 201a					
	AGT , 3034								
	-//		-						

Gold Wing	GOLD WING AVIATION An AIRTRONICS INC. company	REG: N 140RM	WO#: 719	
Aviation	12380 Airport Road, Hangar 6 Jackson, CA 95642 209-418-0004	MAKE: LYCOMING	MODEL: TIO-540-	AF1B
LOCATION: WOODSTON		S/N: L-10413-61A		
LOCATION: INSPECTION		AFTT: 1189.00	TACH: 1189.00	
SERVICE DESCRIPTION:	i			
ENGINE TT: 1189.00				
6) Re-timed both LH and RH tragnetos 7) Replaced both atternator bets PN 3 8) Performed compression check as followed to the second of the compression of the second 10) Removed and Replaced all acrews 11) Replaced fix upper deck pressure second 12) Removed primary and standby vao 13) Removed and replaced 6x cylinder	ited spark plugs in same cylinder, reinstalled/ torqued with new M674 1. Checked tening @ 20' ETOC found satisfactory. 17A19773-470 and 37A19773-380 8ows. 1) 75/80 2) 77/80 3) 77/80 4) 75/80 5) 70/80 6) 76/80 MO)- r cowl. all heat such anger mulf soft lines at injections. bum pumps. Installed Lycoming Accessory cover plate PN: 60430 a	M/80 nd Gaskel SL 8313 gaskel	e found.	
Complied With (CW) AD 2015-19-07 / CW AD 84-26-02 Amendment 39-496	Amendment 39-18269 Dated Nov. 3, 2015 IAW peragraph (e)(1)(ii) a 6 Dated Jen. 28, 1985 IAW peragraph (b) Inspection of induction filter	ed MSB: 342G. No defects found at this time. Next Duo Hobbs: 1289 00	Next Due Hobbs: 1289.00	
conflit this engine has been inspected found to be airworthy. Next due 1 Mary	of IAW FAR 43 App. D and and was det	emined to be airworthy at this time. Perform	od operational n.n of engine and o	ontrols IAW 43.15(c)(2).
	=/			
NAME: RANDY ZIEME	RTS DATE: February 07, 2021			

NA AODM Makes I see see	- Madala TIO E404E4B 6/Nat 40443 644 Ualbar 4000 7
TSMOH: 1202.7 TT: 1202	g Model: TIO-540AF1B S/N: L-10413-61A Hobbs: 1202.7 .7
P/N2524232-2 S/N75279, fuel Pump Work performed in accordance with work performed.	P/N RG17980U/M S/N C4900. applicable maintenance manuals. Operations and/or leak check performed for Work limited to what is stated above
	Daniel Umanzor AP3776498

TITE

Eng		Aviatio	A. LLC 20511 Skywest DR Date Hayward CA 94541 02/24/2022
	40RM Make: 10H: 1253.4 1	100 No.	Model: TIO-540AF1B S/N: L-10413-61A Hobbs: 1253.4
	nagneto P/N 6361 S	/N 99110238 Remov	ew 1 intake gasket P/N 71973. Removed both magnetos for 500 hour inspection. ved and replaced contactor points P/N M3081, distributer gear P/N k3056, gear
gear P perfor	P/N K3823, gear P/N rmed in accordance	M3828, coil P/N M3 with slick overhaul r	13975. Both magnetos bench tested and found to operate correctly. Work manual/ 500H inspection checklist. Magnetos reinstalled on aircraft and med no abnormalities noted at this time.
gear P perfor magne	P/N K3823, gear P/N rmed in accordance eto to engine timing performed in accor	M3828, coil P/N M3 with slick overhaul r set. Runup perform dance with applicab	manual/ 500H inspection checklist. Magnetos reinstalled on aircraft and

The second secon

Engine Otviation	L, LLC 20511 Skywest DR Date Hayward CA 94541 02/24/2022
N140RM Make: Lycoming Mo	del: TIO-540AF1B S/N: L-10413-61A Hobbs: 12
removed and replaced oil filter with new Contamination, no excessive metal found. Schened and tested spark plugs reinstalled tolerance. Cleaned fuel injectors, cleaned for AD2015-19-07 by visual inspection in accordance.	80 #3: 76/80 #4: 76/80 #5: 74/70 #6: 76/80. Drained engine oil H48110-1. Old filter cut open and inspected for excessive metal Serviced engine with 10 QT Aeroshell 15-50 oil and 24OZ Avblend. using new gaskets. Ignition timing checked and found to be within uel screen at fuel servo. Engine washed down with solvent. C/W rdance with MSB 342G no discrepancies noted at this time. Next duair filter IAW paragraph (a)by filter replacement. Inspection Next descriptions.
I Certify that this Engine has been inspected in airworthy condition at this time.	accordance with Part 43 Appendix D (Annual/100H) inspection and is in

.



MCCAULEY

PROPELLER LOGBOOK

- CLOSED -

Owner Name	
Address	
Propeller Model 23732C417-D	
Blade Model G-82 nzb-7	
Hub Serial No. 993540	
Blade Serial No. 1 75 302	
275 313	
3 75 315	
4	

INSTALLATION HISTORY

Date	Aircraft Model & Registration Number	Engine Serial Number & Position
1 7 2000	THIS PROPELLER WAS MANUFACTURED NEW AT McCAULEY PROPELLER SYSTEMS,	(M) 362)
	INSPECTED AND FOUND TO BE AIRWORTHY ON THIS DATE	

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman and Station Certificate Numbers
	N140RM 5 March 2001 100 hour insp Checked hub PROPELLER	McCauley Tach: 134.7 ection for annual co and blades. AD's HAS BEEN INSPI	ARAPAHOE AERO ER ROAD ENGLEWWOD, COLORAD B3D32C417D S/N: 993540 TSN: 134.7 Calendar To empleted this date using the Mooney M2 checked through bi-weekly 2001-03. ECTED IN ACCORDANCE WITH EE IN AN AIRWORTHY CONDITION Michael Nigro A&P	Total Time: 134.7 ime: 1 year 2 months OM inspection form as a guide. I CERTIFY THAT THIS A 100 HOUR INSPECTION N.

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

	Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CW	
	3753 John J. Montgomery Dr	
	San Diego, CA 92123	
MCCAULEY	B3D32C417D	S/N: 993540
N140RM	MOONEY M20M	S/N: 27-0287
4-29-2011	HOBBS: 757.2	
	pection I/A/W Crownair 100 Hour/Annual Inhas been inspected in accordance with an A	
	requested by the owner/operator and list	ed above was repaired and inspected in be airworthy for return to service. Details
	s agency under Work Order #LT-11-05261	

Air 88 Inc. dba CROWNAIR FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

McCauley Propeller

B3D32C417D

S/N: 993540

N140RM

Mooney M20M

S/N: 27-0287

5-01-12

Hobbs: 814.1 Hrs

TSN: 814.1 Hrs

Maintenance performed:

- Completed Annual Inspection I/A/W Crownair 100 Hour/Annual Inspection Checklist, Form CA 105.
- Dressed all propeller blades as required.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order #PA-12-05744.

Air 88 Inc. dba CROWNAIR
FAA Approved Repair Station #CWNR273K
3753 John J. Montgomery Dr.
San Diego, CA 92123

McCauley Propeller

B3D32C417D

S/N: 993540

N140RM

Mooney M20M

S/N: 27-0287

6-03-13

Hobbs: 867.2 Hrs

TSN: 867.2 Hrs

Maintenance performed:

- Completed Annual Inspection using Crownair Aviation Annual/100 Hour Inspection Checklist, Form CA 105.
- Dressed and painted propeller as required.

I certify that this **propeller** has been inspected in accordance with an **Annual Inspection** and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-13-06161.

Air 88 Inc. dba CROWNAIR
FAA Approved Repair Station #CWNR273K
3753 John J. Montgomery Dr.
San Diego, CA 92123

McCauley Propeller

B3D32C417D

S/N: 993540

N140RM

Mooney M20M

S/N: 27-0287

6-09-14

Hobbs: 906.1 Hrs

TSN: 906.1 Hrs

Maintenance performed:

 Completed Annual Inspection using Crownair Aviation Annual/100 Hour Inspection Checklist, Form CA 105.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-14-06581.

Air 88 Inc. dba CROWNAIR

FAA Approved Repair Station #CWNR273K
3753 John J. Montgomery Dr.
San Diego, CA 92123

 McCauley Propeller
 B3D32C417D
 S/N: 993540

 N140RM
 Mooney M20M
 S/N: 27-0287

 6-11-15
 Hobbs: 940.5 Hrs
 TSN: 940.5 Hrs

Maintenance performed:

Completed Annual Inspection using Crownair Aviation Annual/100 Hour Inspection Checklist, Form CA 105.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-15-07126.

Authorized Representative

Note: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Air 88 Inc. dba CROWNAIR

FAA Approved Repair Station #CWNR273K
3753 John J. Montgomery Dr.
San Diego, CA 92123

McCauley Propeller N140RM 6-06-16 B3D32C417D Mooney M20M Hobbs: 974.9 Hrs S/N: 993540

S/N: 27-0287 TSN: 974.9 Hrs

Maintenance performed:

- Completed Annual Inspection using Crownair Aviation Annual/100 Hour Inspection Checklist, Form CA 105.
- Dressed and painted propeller as required.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-16-07651.

F.A.A. AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN/ LETTER COMPLIANCE RECORD

CROWNAIR

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

McCauley Propeller

B3D32C417D

S/N: 993540

N140RM

Mooney M20M

S/N: 27-0287

10-17-17

Hobbs: 1033.7 Hrs

TSN: 1033.7 Hrs

Maintenance performed:

Completed Annual Inspection using Crownair Aviation Annual/100 Hour Inspection Checklist, Form CA 105.
 Researched ADs through bi-weekly issue of this date, all ADs are in compliance at this time.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service. Details of the repair are on file at this agency under Work Order No. PA-17-08124.

F.A.A. AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN/ LETTER COMPLIANCE RECORD

CROWNAIR

FAA Approved Repair Station #CWNR273K 3753 John J. Montgomery Dr. San Diego, CA 92123

McCauley Propeller

N140RM

11-05-18

B3D32C417D

Mooney M20M

Hobbs: 1070.0 Hrs

S/N: 993540

S/N: 27-0287

TSN: 1070.0 Hrs

Maintenance performed:

- Completed Annual Inspection using Crownair Aviation Annual/100 Hour Inspection Checklist, Form CA 105.
- Dressed and painted propeller as required.

I certify that this propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition.

I certify that only the work requested by the owner/operator and listed above was repaired and inspected in accordance with current Federal Aviation Regulations and was found to be airworthy for return to service Details of the repair are on file at this agency under Work Order No. PA-18-08400.



GOLD WING AVIATION An AIRTRONICS INC. company 12380 Airport Road, Hangar 6 Jackson, CA 95642 209-418-0004

REG: N 140RM

WO#: 461

MAKE: McCauley

MODEL: B3D32C417D

5/N: 993540

AFTT: 1116.50

TACH: 1116 50

SERVICE DESCRIPTION:

LOCATION: INSPECTION

PROP TSMOH: 1116.50

I certify this Propeller has been inspected In Accordance With(IAW) an 100 hr. inspection, IAW FAR 43 App. D and was found to be airworthy at this time. Next due JANUARY 1 2021 / AFTT 1216.50

NAME RANDY ZIEMED

RTS DATE: December 09, 2019

Year: Date:	Total Time in Service	Gold ving Aviation	GOLD WING AVIATION An AIRTRONICS INC. company 12380 Airport Road, Hangar 6	REG: N 140RM	WO#: 719	
Next Inspection Due:	Time Since Overhaul	LOCATION: INSPECTION SERVICE DESCRIPTION: PROP TSMOH: 1189	Jackson, CA 95642 209-418-0004	MAKE: McCaulay 5/N: 993540 AFTT: 1189.00	MODEL: 83032C417D TACH: 1189.00	
Year:	Total Time in Service		er, cleaned hub, installed new o , and safetied. Ran engine up o found at this time.			
Next Inspection Due:	Time Since Overhaul		found to be airworthy at this time			
Year:	Total Time in Service	CERT: A&P 3854194	RTS DATE: February 07, 2021			Law elge-
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Re	pair Station #			

HUB	2	BLADE	INSP	ECT	IONS.	REPAIRS	AND	ALTE	RATI	ONS
	•	DEADE			,	HEI MING		~		

ar:	Total Time in Service	Description	065 (100)	110
7040		Aviation, LLC	The second secon	Date
Prope	eller		Hayward CA 94541	02/24/2022
" тѕмс		McCauley Model: B3D32C417-I TT: 1253.4	S/N: 992540 Hobbs:	1253.4
Inspecte		back plate for cracks cleaned and lubed hub ex	terior with LPS. Dressed leading	g edges and coated blades
airwort	that this Prop hy condition at			
aı	III I District II	Exhater	Evan Sath	ner AP3233776IA
te				
xt Inspection e:	Time Since Overhaul			
		Mech. Cert. # or Repair Station #		